

Site Data Form 170A-1

Date of Inspection 2-22-1970

Please type or print in ink:

1. Site Name Old Edina Sentinel Building + Methodist church
2. Site Location
 - a. County Knox, Section _____, Township _____, Range _____
 - b. Town Edina, Street & Number corner of Main + Morgan
3. Present Owner F. E. Schofield Estate - Methodist church
Address Edina Mo
4. Present Use of Site Storage church Building
Historic Use of Site _____
5. Approximate Date of Construction Before 1868 9-20-1898
6. Identification Photograph: Number enclosed 1 Date exposed 2-22-70

Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken.

Photographer's name Junior Wilkerson
Address Novelty MO 63460

7. Construction: a) Wall material stone _____ brick wood frame _____
other (specify) _____
- b) Present condition very good state of repair fair _____
poor _____ much altered _____ ruins _____
8. References: a) Local Histories _____
b) County Historical Atlas 1916 Atlas - 1916 Atlas
c) Local libraries and librarians (give name and address) _____

9. Site is Important Because _____
10. Site Inspector's Name Junior Wilkerson



THE
SENTINEL
PRINTING
OFFICE

THE E

Site Data Form 170A-1

Date of Inspection 2-22-70

Please type or print in ink:

1. Site Name The old Miller wagon Factory
Edina Auction
2. Site Location
- a. County Knox ~~Edina~~, Section _____, Township _____, Range _____
- b. Town Edina, Street & Number Main
3. Present Owner Edina Auction Co
- Address Edina MO
4. Present Use of Site Sale Barn.
- Historic Use of Site _____
5. Approximate Date of Construction After 1897 ~~Before 1916~~
6. Identification Photograph: Number enclosed 1 Date exposed 2-22-70

Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken.

Photographer's name Junior Wilkerson

Address Novelty MO

7. Construction: a) Wall material stone _____ brick X wood frame X
- other (specify) _____
- b) Present condition very good state of repair _____ fair X
- poor _____ much altered _____ ruins _____
8. References: a) Local Histories _____
- _____
- b) County Historical Atlas _____
- c) Local libraries and librarians (give name and address) _____
- _____
- _____

9. Site is Important Because they made lots of wagons and Buggies
here.

10. Site Inspector's Name (J. Wilkerson)

EDINA AUCTION CO.

SALES EVERY FRIDAY



Site Data Form 170A-1

Date of Inspection 2-22-70

Please type or print in ink:

1. Site Name Catholic church

2. Site Location

a. County Knox, Section _____, Township _____, Range _____

b. Town Edina, Street & Number corner of Main & Smallwood

3. Present Owner Catholic church

Address _____

4. Present Use of Site church Building

Historic Use of Site _____

5. Approximate Date of Construction 1873

6. Identification Photograph: Number enclosed 1 Date exposed 2-22-70

Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken.

Photographer's name Junior Wilkerson

Address Novelty Mo

7. Construction: a) Wall material stone _____ brick X wood frame _____

other (specify) _____

b) Present condition very good state of repair X fair _____

poor _____ much altered _____ ruins _____

8. References: a) Local Histories _____

b) County Historical Atlas 1876-1897-1916-

c) Local libraries and librarians (give name and address) _____

9. Site is Important Because _____

10. Site Inspector's Name Junior Wilkerson



Site Data Form 170A-1

Date of Inspection 2-22-70

Please type or print in ink:

1. Site Name The old winter bottom woolen Mills Building

2. Site Location

a. County Knox, Section _____, Township _____, Range _____

b. Town Edina, Street & Number corner of Main & Front

3. Present Owner Hirner

Address Edina, MO

4. Present Use of Site storage up stairs - Auto parts store Bobw

Historic Use of Site _____

5. Approximate Date of Construction Before 1879 -

6. Identification Photograph: Number enclosed 1 Date exposed 2-22-70

Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken.

Photographer's name Junior Wilberson

Address Norelty, MO

7. Construction: a) Wall material stone _____ brick wood frame _____

other (specify) _____

b) Present condition very good state of repair fair _____

poor _____ much altered _____ ruins _____

8. References: a) Local Histories _____

b) County Historical Atlas _____

c) Local libraries and librarians (give name and address) _____

9. Site is Important Because It was and has been the only woolen mill in Knox county - The Bricks were made in southeast part of Edina at the Parker Brick plant.

10. Site Inspector's Name Junior Wilberson



Site Data Form 170A-1

Date of Inspection 2-22-1970

Please type or print in ink:

1. Site Name Knox county court House

2. Site Location

a. County Knox, Section _____, Township _____, Range _____

b. Town Edina, Street & Number public Square

3. Present Owner Knox county

Address _____

4. Present Use of Site court House

Historic Use of Site Knox county Historical Society Museum in one room-

5. Approximate Date of Construction 1934

6. Identification Photograph: Number enclosed 1 Date exposed 2-22-70

Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken.

Photographer's name Junior Wilkerson

Address Novelty MO

7. Construction: a) Wall material stone _____ brick X wood frame _____

other (specify) _____

b) Present condition very good state of repair X fair _____

poor _____ much altered _____ ruins _____

8. References: a) Local Histories _____

b) County Historical Atlas _____

c) Local libraries and librarians (give name and address) _____

9. Site is Important Because _____

10. Site Inspector's Name Junior Wilkerson

Research: Glen Hartley
April, 1972

Knox County
Edina, Mo.

Courthouse of 1935

This brick building has two floors with a recessed entrance area. This area is divided by pilasters into five bays, the second floor with round topped windows and the door in the center bay on the ground floor has a pediment. The roof is flat with a closed balustrade over the entrance area.

DATE: 1935
ARCHITECT:
BUILDER:
COST:
SIZE:
MATERIAL: Brick
Style: Beaux Arts Classicism



KNOX COUNTY COURTHOUSE



Site Data Form 170A-1

Date of Inspection 2-22-70

Please type or print in ink:

1. Site Name Novelty christian church

2. Site Location

a. County Knox, Section _____, Township _____, Range _____

b. Town Novelty, Street & Number state st

3. Present Owner _____

Address _____

4. Present Use of Site church Building

Historic Use of Site _____

5. Approximate Date of Construction 1898

6. Identification Photograph: Number enclosed 1 Date exposed 2-22-70

Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken.

Photographer's name Junior Wilkerson

Address Novelty MO

7. Construction: a) Wall material stone _____ brick _____ wood frame X

other (specify) _____

b) Present condition very good state of repair X fair _____

poor _____ much altered _____ ruins _____

8. References: a) Local Histories _____

b) County Historical Atlas _____

c) Local libraries and librarians (give name and address) _____

9. Site is Important Because _____

10. Site Inspector's Name Junior Wilkerson



Site Data Form 170A-1

Date of Inspection 2-22-70

Please type or print in ink:

1. Site Name Rinehart House

2. Site Location

a. County Knox, Section 29, Township 60, Range 12 W

b. Town _____, Street & Number _____

3. Present Owner W. F. Aucutt

Address Novelty

4. Present Use of Site Home

Historic Use of Site _____

5. Approximate Date of Construction about 1845

6. Identification Photograph: Number enclosed 1 Date exposed 2-22-70

Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken.

Photographer's name Junior Wilkerson

Address Novelty MO

7. Construction: a) Wall material stone _____ brick wood frame _____

other (specify) _____

b) Present condition very good state of repair fair _____

poor _____ much altered _____ ruins _____

8. References: a) Local Histories None

b) County Historical Atlas None

c) Local libraries and librarians (give name and address) None

9. Site is Important Because The time it was built and has

been in the Rinehart family since 1852 - now owned

by the fifth generation, the house and 1200 acres of land
was bought in 1852 for \$5000.00 by Abraham Rinehart - The (over)

10. Site Inspector's Name Junior Wilkerson



Site Data Form 170A-1

Date of Inspection 2-22-70

Please type or print in ink:

1. Site Name Eucebia church

2. Site Location

a. County Knox, Section 29, Township 60, Range 12 W

b. Town _____, Street & Number _____

3. Present Owner _____

Address _____

4. Present Use of Site church Building

Historic Use of Site _____

5. Approximate Date of Construction 1875

6. Identification Photograph: Number enclosed 1 Date exposed 2-22-70

Please label reverse side with site name, location, the compass point of view, the photographer's name and date photograph was taken.

Photographer's name Junior Wilkerson

Address Novelty MO

7. Construction: a) Wall material stone _____ brick _____ wood frame X

other (specify) _____

b) Present condition very good state of repair X fair _____

poor _____ much altered _____ ruins _____

8. References: a) Local Histories None

b) County Historical Atlas None

c) Local libraries and librarians (give name and address) None

9. Site is Important Because Land Donated for site By Abraham Pinchot and church built just like the Eucebia church in Virginia -

10. Site Inspector's Name Junior Wilkerson -



EUCEDIA
1875