


DUTCHTOWN-BENTON PARK WEST-MOUNT PLEASANT ARCHITECTURAL SURVEY MAP

MARCH 2003



Resource Integrity

- excellent
- good to fair
- poor

