



1. Survey number: JP-AS-006-184		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1401	Street (name): E. Hill Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1996	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input type="checkbox"/> C <input checked="" type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 6/6 vinyl sash
24. Vernacular or property type: Minimal Traditional	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style: Minimal Traditional	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape L-shaped	33. Exterior wall cladding: Wood	
27. No. of stories: 1	34. Foundation material CMU	Endangered by:
28. No. of bays (1st floor): 4	35. Basement type: Crawl Space	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Cross-hipped	36. Front porch type/placement: Open, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

This resource was constructed in 1996.

This resource is less than fifty years of age and it does not exhibit exception significance necessary to merit individual listing the National Register. This resource would be non-contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling fronts E. Hill Street to the south and is located in the east portion of the Survey Area. An east-west gravel alley abuts the north edge of the property while a concrete sidewalk abuts the south edge. A concrete walkway leads from the sidewalk to the front porch. An ornamental lawn with deciduous trees characterizes the landscaping. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Minimal Traditional dwelling faces south and has an L-shaped footprint. It has a concrete masonry unit foundation and wood cladding. The hipped roof with cross-gables has asphalt shingles. The dwelling is four bays wide and two asymmetrical bays deep. The west two bays are recessed, creating a partial-width open porch. The porch elements are non-historic. A Non-historic wood door occupies the second-from-west bay while six-over-six vinyl windows occupy the remaining bays.



1401





1. Survey number: JP-AS-006-185		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1402	Street (name): E. Hill Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1900	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input type="checkbox"/> C <input checked="" type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Metal	37. Windows: <input checked="" type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement bands of 1/1 wood sash at porch, 6/6 vinyl sash
24. Vernacular or property type: National Folk	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): Unknown <input checked="" type="checkbox"/> Altered Date(s): Unknown <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Square	33. Exterior wall cladding: Brick, vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 4	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Side-gabled	36. Front porch type/placement: Closed, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: George W. Robbins (Mollie and daughter Naydeen), white, jig man at ore mill, owns home; 1920 city directory: George R. Jones (Daisy) - boilermaker; 1935 city directory: Same as 1940 Census; 1940 Census: George Roy (Jeanne - operator, son - David; son Jack Jones - sheet metal worker), white, boiler maker, owns home, same 1935; 1950 Sanborn: 1-story dwelling; 1960 city directory: Clinton C. Witmer (Katie) - clerk; 1965 city directory: Clinton C. Witmer.

This resource has poor integrity. Non-historic alterations compromise the ability of this resource to convey its historic function and date of construction. This resource would be non-contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling fronts E. Hill Street to the north and is located in the east portion of the Survey Area. An ornamental lawn with sparse mature trees characterizes the landscaping. A concrete walkway leads from the street to the front porch. Not outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This National Folk House dwelling faces north and has a square footprint. It has a concrete foundation and corrugated metal roof. Brick veneer clads the lower third of the enclosed porch at the primary elevation. The remainder of the dwelling has vinyl siding. The dwelling is four asymmetrical bays wide and three bays deep. A three-quarter width enclosed porch with a shed roof contains the three west bays. The porch enclosure is an alteration. One-over-one wood windows occupy the first and third bays of the dwelling while a six-over-six vinyl window occupies the fourth bay. A non-historic wood door with glazing defines the second bay.







1. Survey number: JP-AS-006-186		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1403	Street (name): E. Hill Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1996	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input type="checkbox"/> C <input checked="" type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 6/6 vinyl sash
24. Vernacular or property type: Minimal Traditional	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style: Minimal Traditional	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape L-shaped	33. Exterior wall cladding: Wood	
27. No. of stories: 1	34. Foundation material CMU	
28. No. of bays (1st floor): 4	35. Basement type: Crawl Space	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Cross-gabled	36. Front porch type/placement: Open, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

This resource was constructed in 1996.

This resource is less than fifty years of age and it does not exhibit exception significance necessary to merit individual listing the National Register. This resource would be non-contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling fronts E. Hill Street to the south and is located in the east portion of the Survey Area. An east-west gravel alley abuts the north edge of the property while a concrete sidewalk abuts the south edge. A concrete walkway leads from the sidewalk to the front porch. The ornamental lawn features mature trees and shrubs. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Minimal Traditional dwelling faces south and has an L-shaped footprint. It has a concrete masonry unit foundation and wood cladding. The intersecting gable roof has asphalt shingles. The dwelling is four bays wide and two asymmetrical bays deep. The east two bays recede, creating a partial-width open porch. The porch has a shed roof, concrete foundation, and matchstick balustrade. A wood door with glazing occupies the second-from-east bay while six-over-six vinyl windows occupy the remaining bays.







1. Survey number: JP-AS-006-187		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1404	Street (name): E. Hill Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1890	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input type="checkbox"/> C <input checked="" type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 wood sash
24. Vernacular or property type: National Folk	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): c. 1980 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Stone veneer, wood	Endangered by:
27. No. of stories: 1.5	34. Foundation material Not Visible	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Side-gabled	36. Front porch type/placement: Open, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1940 Census: Amos Reniker (Edith, daughter Constance, sons Donald and Richard; mother-in-law Maude McCary; sister-in-law Thelma P Snelson)), white, florist designer, owns home, Joplin, 1935; 1950 Sanborn: 1.5-story dwelling; 1960 city directory: Earl O. Ball (Sylvia); 1965 city directory: Earl O. Ball.

This resource has poor integrity. The application of stone veneer siding compromises its integrity. This resource would be non-contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling fronts E. Hill Street to the north and is located in the east portion of the Survey Area. Deciduous trees are located at the primary elevation and flank a concrete walkway which leads from the street to the front porch. A gravel drive leads to a garage outbuilding to the southwest. The concrete block garage is located in the southwest corner of the lot. The front-gable roof features asphalt shingles and plywood panels in the gable peak. A pair of hinged wood doors occupy the single bay. It retains fair integrity and would be contributing to a potential historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This National Folk House dwelling faces north and has a rectangular footprint. It has a stone foundation and asphalt shingle roof. Stone and brick veneer clads the primary elevation while wood clapboards clad the secondary elevations. The dwelling is three asymmetrical bays wide and two bays deep. A historic wood door occupies the center bay while historic one-over-one wood windows fill the remaining bays. A non-historic porch with a hipped roof, turned wood support posts, and concrete foundation spans the primary elevation. An enclosed porch projects from the south elevation.







NO
TRESPASSING



1. Survey number: JP-AS-006-188		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1410	Street (name): E. Hill Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1900	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input type="checkbox"/> C <input checked="" type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1-1 metal sliding, 1/1 metal sash
24. Vernacular or property type: Gabled-Ell	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): c.1980 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Non-historic wood	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Cross-gabled	36. Front porch type/placement: N/A	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: Fred C. Wolf (Lura and son Eddie), white, hoisterman for ore mill; rents home; 1920 city directory: George E. McFarland (Lenna) - foreman; 1940 Census: Harry Becker (Lucile, brother Clarence - baker) white; salesman, owns home, Joplin 1935; 1950 Sanborn: 1-story dwelling; 1965 city directory: Jack R. Phillips.

This resource has poor integrity. Non-historic alterations to the siding and the infill of the porch compromise the ability of this resource to convey its historic function and date of construction. It is not eligible or would not contribute to a potential historic district. This resource would be non-contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling fronts E. Hill Street to the north and is located in the east portion of the survey area. The landscaping is characterized by an ornamental lawn with mature trees and shrubs. A concrete walkway leads from the street to the primary entrance. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Gabled-Ell dwelling faces north and has a rectangular footprint. It has a concrete foundation and non-historic wood cladding. The roof has asphalt shingles. The dwelling is three bays wide and three bays deep. An enclosed porch with a shed roof contains the east two bays. The enclosure is an alteration. A non-historic wood door occupies the center bay while a one-by-one metal window occupies the west bay. A pair of one-over-one metal windows with false shutters occupies the west bay. An enclosed shed-roof porch projects from the south elevation.







1. Survey number: JP-AS-006-189		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1411	Street (name): E. Hill Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1910	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input checked="" type="checkbox"/> C <input type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Bungalow/Bungalowoid	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): Unknown <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Irregular	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Not Visible	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Front-gabled	36. Front porch type/placement: Recessed, full-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: Harry W. Sessler (Nellie; sons Frank, Fred, and Guy; daughters Cleo and Dot), white, driver of coal wagon, two oldest sons are transfer drivers, rents home; 1920 city directory: Amos Coley (Mary) - foreman; 1940 Census: Elmer Richards (widowed; Della - mother, widowed), white, warehouse man with wholesale grocer, rents home, Joplin 1935; Crystal Martin (son Lloyd (soil erosion leader CCC, unemployed 120 weeks, and daughter Mary), white, housekeeper; 1950 Sanborn: 1-story dwelling; 1960 city directory: William W. Rowe (Inez) - inspector; 1965 city directory: Charles R. McClain.

This resource has fair integrity. It retains its historic form and porch, sufficient to communicate its historic associations and date of construction. This resource would be contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling fronts E. Hill Street to the south and is located in the east portion of the Survey Area. An east-west gravel alley abuts the north edge of the property while a concrete sidewalk abuts the south edge. A low, concrete retaining wall lines the south edge of the lot. Concrete stairs interrupt the retaining wall and lead to the front porch. A single-bay garage is located in the northeast corner of the lot. The front-gable garage has vinyl siding, a stone foundation, and an asphalt shingle roof. Non-historic wood doors fill the bay. This garage has poor integrity and would be non-contributing to a potential historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This bungalow dwelling faces south and has an irregular footprint. It has vinyl cladding and an asphalt shingle roof. The foundation is not visible. The dwelling is three bays wide and four bays deep. An open porch with a concrete foundation spans the primary elevation. Squared wood columns on concrete piers support the porch roof. A non-historic fiberglass door occupies the center bay of the primary foundation while one-over-one vinyl windows with false shutters occupy the adjacent bays.



1415







1. Survey number: JP-AS-006-190		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1412	Street (name): E. Hill Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1880	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input checked="" type="checkbox"/> C <input type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 wood sash
24. Vernacular or property type:	31. Chimney placement: Center, straddle ridge	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style: Gothic Revival	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Stone	
27. No. of stories: 1.5	34. Foundation material Stone	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Cross-gabled	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1935 city directory: Same as 1940 Census; 1940 Census: Roscoe Wolfe (Anna, sons Frederick and Durwood; daughter-in-law Marlyn), white, painter, rents home, same 1935.; 1950 Sanborn: 1.5-story dwelling; 1960 city directory: Richard L. Erskin (Carolyn) - assembler Hercules Powder; 1965 city directory: Myrl D. Gunn.

This resource has good integrity. This resource would be contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling fronts E. Hill Street to the north and is located in the east portion of the survey area. The lawn is heavily planted with mature trees and shrubs. A non-historic shed with wood panel cladding obscures a front-gable outbuilding with wood cladding in the southeast corner of the lot. This non-historic shed would be non-contributing to the potential historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This two-story Gothic Revival dwelling faces north and has a rectangular footprint. It has a field stone foundation and split-slab field stone cladding. The roof has asphalt shingles and a brick chimney pierces the ridge. The dwelling is three bays wide and one bay deep. An open, three-quarter width historic porch shelters the primary elevation bays. A non-historic wood door occupies the center bay while narrow historic one-over-one wood windows occupy the remaining bays. A historic one-over-one wood window occupies the center gable.











1. Survey number: JP-AS-006-191		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address V35 - 1400 block	Street (name): E. Hill Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Vacant/Not in Use

HISTORICAL INFORMATION

12. Construction date: 2005	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input type="checkbox"/> C <input checked="" type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input type="checkbox"/> building <input checked="" type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: N/A	37. Windows: <input type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement N/A
24. Vernacular or property type: Vacant Lot	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: N/A	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape N/A	33. Exterior wall cladding: N/A	Endangered by:
27. No. of stories: N/A	34. Foundation material N/A	
28. No. of bays (1st floor):	35. Basement type: N/A	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: N/A	36. Front porch type/placement: N/A	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district	Other:	
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

The resources historically constructed on this lot were demolished c.2005. It remains vacant.

This resource has poor integrity due to the demolition of buildings previously constructed on the lot. This resource would be non-contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This vacant lot occupies the northwest corner of the intersection of E. Hill Street and N. Garden Ave. It is dotted with mature trees. An east-west gravel alley abuts the north edge of the property while a concrete sidewalk abuts the south and east edges.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This grassy lot is vacant.





1. Survey number: JP-AS-006-192		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1501	Street (name): E. Hill Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1905	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input checked="" type="checkbox"/> C <input type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Shotgun	31. Chimney placement: Offset rear, straddle ridge	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): c.1960 <input checked="" type="checkbox"/> Altered Date(s): c.2000 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Irregular	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 2	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Front-gabled	36. Front porch type/placement: Veranda, full-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: Samuel P. Saunders, Joseph (son) and Minnie (daughter-in-law), white. Father has own income while son is a retail merchant for a grocery, owns home; 1920 city directory: Fred Mitchell (Letha) - employee Empire Dist. Elec. Co.; 1950 Sanborn: 1-story dwelling; 1960 city directory: Walter E. Smith; 1965 city directory: Mrs. Myrtle Nadler.

This resource has fair integrity. It retains its historic form (including the historic east addition) that conveys its historic associations and era of construction. This resource would be contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling fronts E. Hill Street to the south and is located in the east portion of the survey area. A chain-link fence encircles the ornamental lawn and an east-west gravel alley abuts the north edge of the property. A historic single-bay garage is located at the northwest corner of the lot. The garage has wood clapboard cladding and a rectangular footprint. The front-gable roof features asphalt shingles and exposed rafter tails. The metal overhead garage door is non-historic. This garage has good integrity and would be contributing to a potential historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Shotgun dwelling faces south and has an irregular footprint. It has a concrete foundation, vinyl cladding, and asphalt shingle roof. A shed-roof addition projects from the east elevation. A non-historic porch with front-gable roof and metal support posts shelters the primary elevation bays. A non-historic wood door occupies the east bay while a one-over-one vinyl window occupies the west bay. Windows at secondary elevations have non-historic awnings. The east addition is not present on the 1950 Sanborn Map, but is present in the 1961 aerial photograph.



1501

E Hill St

1501







1. Survey number: JP-AS-006-193		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1505	Street (name): E. Hill Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Vacant/Not in Use

HISTORICAL INFORMATION

12. Construction date: 2012	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input type="checkbox"/> C <input checked="" type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input type="checkbox"/> building <input checked="" type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: N/A	37. Windows: <input type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement N/A
24. Vernacular or property type: Vacant Lot	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: N/A	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape N/A	33. Exterior wall cladding: N/A	
27. No. of stories: N/A	34. Foundation material N/A	Endangered by:
28. No. of bays (1st floor):	35. Basement type: N/A	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: N/A	36. Front porch type/placement: N/A	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

The resources historically constructed on this lot were demolished c.2012. It remains vacant.

This resource has poor integrity due to the demolition of buildings previously constructed on the lot. This resource would be non-contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling fronts E. Hill Street to the south and is located in the east portion of the survey area. An east-west gravel alley abuts the north edge of the property and a concrete sidewalk abuts the south edge. The vacant lot is dotted with mature trees.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This grassy lot is vacant.





1. Survey number: JP-AS-006-194		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1509	Street (name): E. Hill Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Vacant/Not in Use

HISTORICAL INFORMATION

12. Construction date: 2012	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input type="checkbox"/> C <input checked="" type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input type="checkbox"/> building <input checked="" type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: N/A	37. Windows: <input type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement N/A
24. Vernacular or property type: Vacant Lot	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: N/A	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape N/A	33. Exterior wall cladding: N/A	
27. No. of stories: N/A	34. Foundation material N/A	Endangered by:
28. No. of bays (1st floor):	35. Basement type: N/A	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: N/A	36. Front porch type/placement: N/A	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

The resources historically constructed on this lot were demolished c.2012. It remains vacant.

This resource has poor integrity due to the demolition of buildings previously constructed on the lot. This resource would be non-contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling fronts E. Hill Street to the south and is located in the east portion of the survey area. An east-west gravel alley abuts the north edge of the property and a concrete sidewalk abuts the south edge. The vacant lot is dotted with mature trees.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This grassy lot is vacant.





1. Survey number: JP-AS-006-195		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1513	Street (name): E. Hill Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Vacant/Not in Use

HISTORICAL INFORMATION

12. Construction date: 2012	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input type="checkbox"/> C <input checked="" type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input type="checkbox"/> building <input checked="" type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: N/A	37. Windows: <input type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement N/A
24. Vernacular or property type: Vacant Lot	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: N/A	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape N/A	33. Exterior wall cladding: N/A	
27. No. of stories: N/A	34. Foundation material N/A	Endangered by:
28. No. of bays (1st floor):	35. Basement type: N/A	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: N/A	36. Front porch type/placement: N/A	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

The resources historically constructed on this lot were demolished c.2012. It remains vacant.

This resource has poor integrity due to the demolition of buildings previously constructed on the lot. This resource would be non-contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling fronts E. Hill Street to the south and is located in the east portion of the survey area. An east-west gravel alley abuts the north edge of the property and a concrete sidewalk abuts the south edge. The vacant lot is dotted with mature trees.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This grassy lot is vacant.





1. Survey number: JP-AS-006-196		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1517	Street (name): E. Hill Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1915	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input type="checkbox"/> C <input checked="" type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Metal	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Other Vernacular	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): c.2014 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape L-shaped	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 4	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Side-gabled	36. Front porch type/placement: Platform	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1920 city directory: Jeff Jackson (Lizzie) - smelter; 1940 Census: William H. Karch (Katy), white, water carrier WPA, owns home, Phelps MO 1935; 1950 Sanborn: 1-story dwelling; 1960 city directory: Donald R. Allen (Betty) - employee City Garbage Disposal; 1965 city directory: vacant.

This resource has poor integrity. Non-historic alterations, including the application of non-historic siding that covers the entire south façade obscuring the historic entrance and any indication that there was once a porch there, as well as the replacement of windows and roof compromise the ability of this resource to convey its historic function and date of construction. This resource would be non-contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The lot fronts E. Hill Street to the south and is located in the east portion of the Survey Area. An ornamental lawn, shrubs, and mature trees characterize the landscape. An east-west gravel alley abuts the north edge of the property. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This dwelling faces south and has an L-shaped footprint. An enclosed porch contains the north two bays of the east elevation. The dwelling has a concrete foundation, vinyl cladding, and a seamed metal gabled roof. It is four bays wide. A non-historic wood door with glazing occupies the second bay while one-over-one vinyl windows occupy the remaining bays. The 2013 Google Street View shows that the northeast porch was already enclosed with historic wood siding and the south elevation had a single door and a window, both of which have been infilled. The south porch had been removed prior to 2007.







1. Survey number: JP-AS-006-197		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address V36 - 1500 block	Street (name): E. Hill Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Vacant/Not in Use

HISTORICAL INFORMATION

12. Construction date: 1980	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input type="checkbox"/> C <input checked="" type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input type="checkbox"/> building <input checked="" type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: N/A	37. Windows: <input type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement N/A
24. Vernacular or property type: Vacant Lot	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: N/A	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape N/A	33. Exterior wall cladding: N/A	
27. No. of stories: N/A	34. Foundation material N/A	Endangered by:
28. No. of bays (1st floor):	35. Basement type: N/A	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: N/A	36. Front porch type/placement: N/A	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

The resources historically constructed on this lot were demolished c.1980. It remains vacant.

This resource has poor integrity due to the demolition of buildings previously constructed on the lot. This resource would be non-contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This vacant lot occupies the northwest corner of the intersection of E. Hill Street and N. McKee Ave. It is dotted with mature trees. An east-west gravel alley abuts the north edge of the property while a concrete sidewalk abuts the south and east edges. A small concrete pad stands at the center of the lot.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This grassy lot is vacant.





1. Survey number: JP-AS-006-198		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1601	Street (name): E. Hill Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1955	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input type="checkbox"/> C <input checked="" type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 6/6 vinyl sash
24. Vernacular or property type: Gabled-Ell	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): c.2010 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape L-shaped	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Parged	
28. No. of bays (1st floor): 3	35. Basement type: None	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Cross-gabled	36. Front porch type/placement: Open, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1960 city directory: Lawrence A. Attwood (Dorothy) - painter; 1965 city directory: Mrs. Dorothy Attwood.

This resource has poor integrity. The installation of vinyl siding, vinyl windows, and the alteration of the fenestration compromise the integrity of this resource so it no longer communicates historic associations or the date of construction. This resource would be non-contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The lot fronts E. Hill Street to the south and is located in the east portion of the Survey Area. An east-west gravel alley abuts the north edge of the property. An ornamental lawn with mature trees and planting beds characterizes the landscaping. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Gabled-ElI dwelling faces south and has an L-shaped footprint. It has a parged foundation and vinyl cladding. The roof has asphalt shingles. The dwelling is three bays wide and two bays deep. The east two bays recede, creating a partial-width open porch. The porch has a shed roof and concrete foundation. The masonry walls and piers are parged. A non-historic wood door with non-light glazing occupies the center bay at the primary elevation while a six-over-six vinyl window occupies the west bay and a six-over-six wood window occupies the east bay.







1. Survey number: JP-AS-006-199		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1611	Street (name): E. Hill Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1910	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input checked="" type="checkbox"/> C <input type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 wood sash
24. Vernacular or property type: Gabled-Ell	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): c.1955 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape T-shaped	33. Exterior wall cladding: Asbestos	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 4	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Cross-gabled	36. Front porch type/placement: Closed, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: Lydia P. Bardmass (son Claude, daughter Jennie), white, widowed, son works as grocery delivery, rents home; 1920 city directory: George W. Donahoe (Grace) - contractor; 1940 Census: Gerald L. Stultz (Vera M), white, police detective, owns home, Joplin and Los Angeles, same in 1935.; 1950 Sanborn: 1-story dwelling; 1960 city directory: Albert J. Millman (Florence) - plumber; 1965 city directory: Albert J. Millman.

This resource has good integrity. This resource would be contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts E. Hill Street to the south and is located in the east portion of the Survey Area. An east-west gravel alley abuts the north edge of the property while a concrete sidewalk and retaining wall abuts the east edge. An ornamental lawn with mature trees and scrub characterizes the landscaping. A historic two-bay garage outbuilding is located in the northwest corner of the lot. The front-gable roof has asphalt shingles. Hexagonal shingles characterize the gable ends. The garage has asbestos shingle cladding and the foundation is not visible. A historic sliding wood door occupies the primary elevation bay while a pedestrian entrance and historic one-light wood window are located at the secondary elevation. This garage has good integrity and would be contributing to a potential historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Gabled-Ell dwelling faces east and has a T-shaped footprint. It has a concrete foundation, asbestos shingle cladding, and asphalt shingle roof. The dwelling is three bays wide and two bays deep. A historic enclosed shed-roof porch with jalousie windows defines the center bay. One-over-one metal windows with flat board trim define the remaining bays. The primary entrance door is not visible.









1. Survey number: JP-AS-006-200		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 102	Street (name): N. Landreth Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1920	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1965	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Commerce, Transportation, Community Planning & Development	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input type="checkbox"/> C <input checked="" type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Bungalow/Bungalowoid	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): 2017 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Hardboard	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 3	35. Basement type: None	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Front-gabled	36. Front porch type/placement: Wraparound, veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1935 city directory: Same as 1940 Census; 1940 Census: Eva Inman, white, owns home, same 1935; 1950 Sanborn: 1-story dwelling; 1960 city directory: George W. Kohler.

This resource has poor integrity. Non-historic alterations, including the application of non-historic siding and the alteration of window openings and porch materials, compromise the ability of this resource to convey its historic function and date of construction. However, this is a work in progress. If a nomination moves forward, this resource may be evaluated to have retained sufficient integrity to be a contributing resource. This resource would be non-contributing to the potential East Joplin/Original Town Historic District, significant for its associations with the early commercial and residential development of Joplin, as well as its associations with Route 66. Areas of significance are Commerce, Transportation, and Community Planning & Development. There is potential for this district to include resources on the south side of E. Broadway, to be surveyed in Phase II.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This dwelling fronts N. Landreth Avenue to the east and is located in the west portion of the Survey Area. It has a narrow setback and ornamental lawn with mature trees. A concrete sidewalk abuts the east edge of the property. A front-gabled two-car garage with asbestos shingle siding and an asphalt shingle roof. Asphalt singles clad the gable end. The wide opening has two sliding wood doors. The garage retains good integrity and would be contributing to a potential historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Open Gable dwelling faces east and has a rectangular footprint. It has a concrete foundation and pressboard cladding. The front-gable roof has asphalt shingles. The dwelling is three bays wide and three bays deep. A front-gable roof shelters the south two bays of the primary elevation. The porch wraps around the south elevation has a concrete foundation and brick piers. Brick steps are located at the southeast corner. Non-historic wood posts support the roof. A non-historic wood door with glazing occupies the south bay while one-over-one vinyl windows fill the remaining bays. The new windows are smaller than the original openings and thus have wood infill. It is unknown what the new siding material will be.







1. Survey number: JP-AS-006-201		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 112	Street (name): N. Landreth Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1930	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1965	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Commerce, Transportation, Community Planning & Development	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input checked="" type="checkbox"/> C <input type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Bungalow/Bungalowoid	31. Chimney placement: Center, straddle ridge	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): c.2010 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape L-shaped	33. Exterior wall cladding: Stone	Endangered by:
27. No. of stories: 1.5	34. Foundation material Concrete	
28. No. of bays (1st floor): 2	35. Basement type: Partial	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Front-gabled	36. Front porch type/placement: Open, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district	Other:	
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1940 Census: Sadie Cleaver (son Jack - laborer, daughter-in-law Helen - housewife), white, owns home; 1950 Sanborn: 1-story dwelling; 1960 city directory: Paule E. Smith (Mildred) - sales manager Dr. Pepper Bottling Co..

This resource has good integrity. This resource would be contributing to the potential East Joplin/Original Town Historic District, significant for its associations with the early commercial and residential development of Joplin, as well as its associations with Route 66. Areas of significance are Commerce, Transportation, and Community Planning & Development. There is potential for this district to include resources on the south side of E. Broadway, to be surveyed in Phase II.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This dwelling fronts N. Landreth Avenue to the east and is located in the west portion of the Survey Area. An ornamental lawn characterizes the landscaping and a concrete sidewalk abuts the east edge of the property. A wood frame carport with a gabled-roof is located west of the dwelling. It is non-historic and would be non-contributing to a potential historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This bungalow dwelling faces east and has a L-shaped footprint. It has a concrete foundation and cut stone cladding. The front-gable roof features asphalt shingles and two straddle-ridge brick chimneys. A shed roof dormer is located on the south slope. An enclosed porch with a gabled roof projects from the south elevation. The dwelling is two bays wide and four bays deep. A front-gable porch with concrete foundation shelters the south primary elevation bay. The porch features cut stone walls and piers. A non-historic door occupies the south bay while a set of three one-over-one vinyl windows occupies the north bay. The dwelling windows have stone sills.









1. Survey number: JP-AS-006-202		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 115	Street (name): N. Landreth Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1906	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1965	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Commerce, Transportation, Community Planning & Development	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input checked="" type="checkbox"/> C <input type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 wood sash
24. Vernacular or property type: Gabled-Ell	31. Chimney placement: center, front slope	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Irregular	33. Exterior wall cladding: Brick	
27. No. of stories: 1	34. Foundation material Stone	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Hipped with lower cross-gable	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1906 Sanborn: From Plans; 1910 Census: ; 1940 Census: Albert Arterburn (Elizabeth, daughters Hazel (house maid) and Alice (factory worker), son Jesse (cashier at meat market)), white, miner for zinc, owns home; 1950 Sanborn: 1-story dwelling; 1960 city directory: Hazel Arterburn - widow.

This resource has excellent integrity. This resource would be contributing to the potential East Joplin/Original Town Historic District, significant for its associations with the early commercial and residential development of Joplin, as well as its associations with Route 66. Areas of significance are Commerce, Transportation, and Community Planning & Development. There is potential for this district to include resources on the south side of E. Broadway, to be surveyed in Phase II.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The lot fronts N. Landreth Avenue to the west and is located in the west portion of the survey area. A gravel east-west alley abuts the south edge of the property while a concrete sidewalk abuts the west edge. A concrete retaining wall abuts the sidewalk. A large tree is located in the southeast corner of the ornamental lawn while a gravel drive is located in the northeast corner. A garage outbuilding with a rectangular footprint and side-gable roof is located in the southeast corner of the lot. It has an asphalt shingle roof with exposed rafter tails and stone cladding. Historic four-light wood windows are located in the gable peaks. A historic wood vehicular door is located at the primary elevation. Historic six-over-six wood windows are present at all elevations visible from the right-of-way. The garage has good integrity and would be contributing to a potential historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This dwelling faces west and has an irregular footprint. An outbuilding is connected to the dwelling at the southeast corner. The dwelling has a stone foundation and brick cladding. The hipped roof with cross-gable has asphalt shingles. Brackets and cornice returns characterize the roof. The dwelling is three bays wide and three bays deep. The north primary elevation bay recedes, creating a partial-width open porch. The historic porch features a concrete foundation and a shallow hipped roof with exposed rafter tails. Tapered wood columns on brick piers support the roof. A historic wood door with a transom occupies the north bay while a matching door with transom is located on the south wall of the porch. A historic two-over-two wood window occupies the center bay while a historic one-over one wood window fills the south bay. Matching windows are present at the secondary elevations. All windows have stone sills.













1. Survey number: JP-AS-006-203		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 116	Street (name): N. Landreth Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1910	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1965	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Commerce, Transportation, Community Planning & Development	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input checked="" type="checkbox"/> C <input type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type:	31. Chimney placement: Offset rear, straddle ridge	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style: Craftsman/Bungalow	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): c.2000 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Brick	Endangered by:
27. No. of stories: 1	34. Foundation material Brick	
28. No. of bays (1st floor): 3	35. Basement type: Partial	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Front-gabled	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: George W. Hill (Mandy) - contractor; Charles Carskadow (boarder) - baggage transfer; white, rents home; 1920 city directory: J.C. Runyon (Eliza) - Contractor; 1940 Census: James Ashley (Reba - booker and stenographer; mother-in-law Hattie Quigley), white, officer, owns home; 1950 Sanborn: 1-story dwelling; 1960 city directory: Bert R. Russell (Viva) - Bert R. Russell Transfer & Storage.

This resource has good integrity. This resource would be contributing to the potential East Joplin/Original Town Historic District, significant for its associations with the early commercial and residential development of Joplin, as well as its associations with Route 66. Areas of significance are Commerce, Transportation, and Community Planning & Development. There is potential for this district to include resources on the south side of E. Broadway, to be surveyed in Phase II.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The lot fronts N. Landreth Avenue to the east and is located in the west portion of the survey area. An east-west gravel alley abuts the north edge of the property while a concrete sidewalk abuts the east edge. An ornamental lawn with mature trees characterizes the landscaping. A historic garage outbuilding is located in the northwest corner of the lot. It is three bays wide and one bay deep. The side-gable roof has asphalt shingles and the cladding is red brick. Buff brick accents mimic the quoins and lintels of the dwelling. A historic wood pedestrian door occupies the south bay while a historic four-light window occupies the center bay. The north vehicular bay has been partially infilled with plywood panels and contains a historic hinged wood door. This garage has good integrity and would be contributing to a potential historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This bungalow dwelling faces east and has a rectangular footprint. It has a concrete block foundation and brick cladding with stone quoins. The front-gable roof features brackets at the gable end and asphalt shingles. A square window opening with a stone sill and lintel occupies the gable peak. The dwelling is three bays wide three bays deep. An open, three-quarter width porch shelters the primary elevation bays. It has a concrete block foundation and shallow hipped roof. Tapered wood columns on brick piers support the roof. A non-historic wood door with glazing occupies the center bay while one-over-one vinyl windows fill the remaining bays. The windows have stone sills. One-over-one vinyl windows with stone sills and lintels are present at the secondary elevations.









1. Survey number: JP-AS-006-204		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 215	Street (name): N. Landreth Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1920	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Metal	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 wood sash
24. Vernacular or property type: Ranch	31. Chimney placement: Center, rear slope	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): c.2000 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Metal	Endangered by:
27. No. of stories: 1	34. Foundation material Not Visible	
28. No. of bays (1st floor): 5	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Side-gabled	36. Front porch type/placement: Recessed, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1960 city directory: Mrs. Mildred Barber.

This resource has fair integrity. It is not eligible because there is no concentration resources to constitute a historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The lot fronts N. Landreth Avenue to the west and is located in the west portion of the Survey Area. Mature trees and shrubs characterize the landscaping. A gravel driveway is located south of the dwelling and leads to a detached garage. The two-bay garage has a rectangular footprint and a front-gable roof with exposed rafter tails. It has wood cladding and the foundation is not visible. The south bay has a non-historic wood door while the north bay is open. This garage has poor integrity and is not eligible.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Ranch dwelling faces west and has a rectangular footprint. It has metal cladding and a seamed metal roof with a center gable. The foundation is not visible. The dwelling is four bays wide and two bays deep. One-over-one wood windows with false shutters occupy the north two bays. A wood door forms the third bay and a one-over-one wood window occupies the south bay. The south two bays recede, creating a partial-width open porch. Wood columns support the porch roof.









1. Survey number: JP-AS-006-205		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 501	Street (name): N. Landreth Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1890	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 wood sash
24. Vernacular or property type: Gabled-Ell	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Square	33. Exterior wall cladding: Wood	
27. No. of stories: 1	34. Foundation material Not Visible	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Cross-hipped	36. Front porch type/placement: Recessed, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1920 city directory: James Laughter (Nora) - employee KC Southern Railway; 1960 city directory: James R. Laughter (Odessa) - employee Safeway.

This resource has good integrity. It is not eligible because there is no concentration of resources to constitute a historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Landreth Avenue to the west and is located in the west portion of the Survey Area. It has a deep setback and mature trees and shrubs partially obscure the dwelling. A gravel driveway leads to the carport. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This dwelling faces south and has a square footprint. It has wood clapboard cladding and an asphalt shingle roof. The foundation is not visible. The dwelling is three bays wide. The west two bays recede, creating a partial-width open porch with a shed roof. Non-historic wood posts support the porch roof. One-over-one metal windows occupy the first and third bays. The primary entrance occupies the center bay; however, the door is not visible. A shed-roof carport projects from the east elevation.







1. Survey number: JP-AS-006-206		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 823	Street (name): N. Landreth Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1900	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 8/8 vinyl sash
24. Vernacular or property type: National Folk	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): c.2010 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Side-gabled	36. Front porch type/placement: N/A	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1935 city directory: Same as 1940 Census; 1940 Census: Earl Douglas (Elsie; daughters Thelma, Elizabeth, and Betty Jean - 2 work as seamstress in shirt factory; son Earl Jr. - apparatus glass cutter; niece Estelene Winfrey; nephews Daniel and Marion Winfrey), white, janitor at library, rents home, same 1935; 1960 city directory: William S. Vicary (Doris) - salesman Ace Hi Liquor.

This resource has fair integrity. It is not eligible because there is no concentration resources to constitute a historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Landreth Avenue to the west and is located in the northwest portion of the Survey Area. Mature trees surround the dwelling and a concrete walkway leads to the front porch. A detached garage outbuilding is located in the northwest corner of the lot. It has a rectangular footprint, wood cladding, and corrugated metal front-gable roof with exposed rafter tails. Historic hinged wood doors occupy the single vehicular bay. This garage has good integrity but it is not eligible because there is no concentration resources to constitute a historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This dwelling faces west and has a rectangular footprint. It has a concrete foundation and hipped-gable roof with asphalt shingles. The primary elevation is vinyl-clad while the secondary elevations have metal siding. The dwelling is three bays wide and two bays deep. A non-historic enclosed stoop with a front-gable roof, concrete foundation, and vinyl cladding obscures the center bay of the primary elevation. It features a non-historic metal door with glazing and obscures the non-historic wood primary entrance door. Eight-over-eight vinyl windows occupy the north and south bays of the primary elevation. Eight-over-eight vinyl windows occupy the first-story bays of the secondary elevations while one-by-one windows are present in the gable ends.









1. Survey number: JP-AS-006-207		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 827	Street (name): N. Landreth Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1992	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1-pane fixed
24. Vernacular or property type:	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style: Modern Movement	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Irregular	33. Exterior wall cladding: Stucco	
27. No. of stories: 1	34. Foundation material Not Visible	Endangered by:
28. No. of bays (1st floor): 5	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Cross-gabled	36. Front porch type/placement: N/A	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

This resource was constructed in 1992.

This resource is less than fifty years of age and it does not exhibit exception significance necessary to merit individual listing the National Register. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Landreth Avenue to the west and is located in the northwest portion of the Survey Area. A concrete drive wraps around the dwelling and a chain-link fence encircles the lawn. A stone retaining wall lines the west edge of the property. Aerial images indicate the presence of at least two outbuildings, but these cannot be confirmed from the public right-of-way due to the dense brush and fencing.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This dwelling faces west and has an irregular footprint. It is heavily obscured by fencing and brush, making it difficult to photograph from the public right-of-way. The complex roof has asphalt shingles and the foundation is not visible. It has stone veneer panel cladding.





PRIVATE
PROPERTY

216





1. Survey number: JP-AS-006-208		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 901	Street (name): N. Landreth Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1920	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 2/2 wood sash
24. Vernacular or property type: Minimal Traditional	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style: Minimal Traditional	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape L-shaped	33. Exterior wall cladding: Brick	
27. No. of stories: 1	34. Foundation material Not Visible	Endangered by:
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Side-gabled	36. Front porch type/placement: Portico	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1920 city directory: Adolphus Lawrence (Lily) - flagman KC Southern Railway; 1935 city directory: Same as 1940 Census; 1940 Census: Katharine Lawrence, white, retired, owns home, same 1935; 1960 city directory: Gene C. Copeland (Leona) - Deputy Sheriff.

This resource has good integrity. It is not eligible because there is no concentration resources to constitute a historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Landreth Avenue to the west and is located in the northwest portion of the Survey Area. The front lawn is terraced with brick bulwarks and stairs. A concrete walkway leads to the front porch while a paved driveway leads to the carport. A detached garage is located in the northeast corner of the lot. It has a side-gable roof and wood cladding. The foundation is not visible. A non-historic metal door occupies the single visible bay of the west elevation. This outbuilding is less than fifty years of age and is not eligible.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This dwelling faces west and has an L-shaped footprint. It has brick cladding and an asphalt shingle roof. The foundation is not visible. The dwelling is three bays wide and four bays deep. A non-historic fiberglass door occupies the center bay of the primary elevation while historic two-over-two wood windows with header brick sills occupy the remaining bays. A frame carport projects from the north elevation and shelters a secondary entrance.









1. Survey number: JP-AS-006-209		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 903	Street (name): N. Landreth Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1920	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 2/2 wood sash
24. Vernacular or property type: Ranch	31. Chimney placement: center, exterior	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: exterior	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Brick	
27. No. of stories: 1	34. Foundation material Not Visible	
28. No. of bays (1st floor): 5	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Cross-gabled	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1920 city directory: B. Frank Reynolds (Mildred) - fire department; 1935 city directory: Same as 1940 Census; 1940 Census: Frank B. Reynolds (Mildred, daughter Mildred Christine - house maid, unemployed 52 weeks), white, custodian at high school, owns home, same 1935; 1960 city directory: Paul B. Edward (Virginia).

This resource has excellent integrity. It may not have the level of significance required of individual listing. It is not eligible because there is no concentration of resources to constitute a historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Landreth Avenue to the west and is located in the northwest portion of the Survey Area. A scored concrete retaining wall with concrete steps lines the west edge of the property. A concrete walkway leads to the front porch while a paved driveway leads to the attached garage. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This dwelling faces west and has a rectangular footprint. It has brick cladding and an asphalt shingle roof. The foundation is not visible. The dwelling is five bays wide. A non-historic overhead garage door occupies the north bay while a wood door with sidelights fills the adjacent bay. The second bay is slightly recessed, creating a recessed stoop. Two-over-two wood windows occupy the third and fifth bays while a tripartite picture window fills the fourth bay. The picture window features a single-light wood window flanked by two-over-two wood windows. A front-gable porch with brick support pillars projects from the south elevation. An exterior brick chimney is located at the southwest corner of the dwelling.







1. Survey number: JP-AS-006-210		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 905	Street (name): N. Landreth Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1930	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 3/1 wood sash
24. Vernacular or property type: Bungalow/Bungaloid	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Asbestos	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 3	35. Basement type: None	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Front-gabled	36. Front porch type/placement: Closed, full-width, 1 story	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1935 city directory: Same as 1940 Census; 1940 Census: Reva Pyles (widowed; daughters Betty Jean and Marjorie Helen; parents John & Mary Hutchins, retired), white, power machine operator at factory, unemployed 16 weeks, rents home, same 1935; 1960 city directory: Mrs. Dorothy Vanhooser - office worker Freeman Hospital.

This resource has excellent integrity, but it may not have the level of significance required of individual listing. It is not eligible because there is no concentration resources to constitute a historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Landreth Avenue to the west and is located in the northwest portion of the Survey Area. An ornamental lawn with mature trees characterizes the landscaping. A gravel drive at the north end of the lot leads to a two-bay garage. The garage has a front-gable roof and wood clapboard cladding. A pair of hinged plywood doors occupies the north bay while a plywood pedestrian door and hisotric four-light wood window occupy the south bay. This garage has good integrity. It is not eligible because there is no concentration resources to constitute a historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This bungalow dwelling faces west and has a rectangular footprint. It has a concrete foundation and asbestos shingle cladding. The front-gable roof has asphalt shingles. The dwelling is three bays wide and five bays deep. An enclosed porch spans the primary elevation. A historic wood door with three-light glazing occupies the center bay of the primary elevation. Sets of three historic three-over-one wood windows occupies the north and south bays. The entrance features a concrete stoop with a front gable roof. The stoop roof features exposed rafter tails and knee brackets.









1. Survey number: JP-AS-006-211		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 909	Street (name): N. Landreth Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1930	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 3/1 wood sash
24. Vernacular or property type: Gabled-Ell	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): Unknown <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape L-shaped	33. Exterior wall cladding: Stucco	Endangered by:
27. No. of stories: 1.5	34. Foundation material Not Visible	
28. No. of bays (1st floor): 5	35. Basement type: None	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Cross-gabled	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1935 city directory: Same as 1940 Census; 1940 Census: Amanda Hill, widowed, retired, rents home, same 1935; 1960 city directory: Mrs. Georgia E. Flint - widow.

This resource has good integrity. It is not eligible because there is no concentration of resources to constitute a historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Landreth Avenue to the west and is located in the northwest portion of the Survey Area. An ornamental lawn with mature trees characterizes the landscaping. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Gabled-Ell dwelling faces west and has an L-shaped footprint. It has stucco cladding and an asphalt shingle roof. The foundation is not visible. The dwelling is five bays wide. Historic three-over-one wood windows occupy the first, third, and fifth bays while a historic wood door with three-light glazing occupies the second bay. A one-over-one aluminum window and wood infill occupies a former entrance opening in the fourth bay and a one-over-one vinyl window is located in the gable peak. The north three bays are recessed, creating an open, partial-width porch. The porch has a shed roof and concrete foundation. Non-historic turned wood posts on parged piers support the roof.



909







1. Survey number: JP-AS-006-212		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 911	Street (name): N. Landreth Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1920	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 metal sash
24. Vernacular or property type: Bungalow/Bungaloid	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): Unknown <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Asbestos	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 2	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Front-gabled	36. Front porch type/placement: Portico	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1920 city directory: Byron Bolles (Ella) - flagman KC Southern Railway; 1940 Census: Ollie P. Flint (Georgia), white, laborer, owns home, Cherryvale 1935; 1950 Sanborn: ; 1960 city directory: vacant.

This resource has good integrity. It is not eligible because there is no concentration resources to constitute a historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Landreth Avenue to the west and is located in the northwest portion of the Survey Area. An ornamental lawn with mature trees characterizes the landscaping. Concrete steps and a concrete walkway lead from the street to the front porch. A gravel drive leads to a detached garage. A single-bay detached garage is located directly north of the dwelling. It has a concrete foundation and asbestos shingle cladding. The front-gable roof has asphalt shingles and wide eaves. A non-historic overhead garage door occupies the primary elevation bay. This garage has good integrity but it is not eligible because there is no concentration resources to constitute a historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This bungalow dwelling faces west and has a rectangular footprint. It has asbestos shingle cladding, concrete foundation, and a front-gable roof with asphalt shingles. The dwelling is two bays wide and three bays deep. A non-historic wood door occupies the north bay of the primary elevation while a pair of one-over-one wood windows occupies the south bay. The windows feature non-historic false shutters and a non-historic wood lintel with keystone detail. A front-gable porch shelters the entrance. It has a concrete foundation and non-historic wood support posts.





911





1. Survey number: JP-AS-006-213		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 107	Street (name): N. McKee Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Vacant/Not in Use

HISTORICAL INFORMATION

12. Construction date: 2015	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input type="checkbox"/> C <input checked="" type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input type="checkbox"/> building <input checked="" type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: N/A	37. Windows: <input type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement N/A
24. Vernacular or property type: Vacant Lot	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: N/A	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape N/A	33. Exterior wall cladding: N/A	
27. No. of stories: N/A	34. Foundation material N/A	
28. No. of bays (1st floor):	35. Basement type: N/A	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: N/A	36. Front porch type/placement: N/A	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

The resources historically constructed on this lot were demolished c.2015. It remains vacant.

This resource has poor integrity due to the demolition of buildings previously constructed on the lot. This resource would be non-contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This vacant lot occupies the southeast corner of the intersection of E. Hill Street and N. McKee Ave. in the southeast portion of the Survey Area. The vacant lot is covered with grass and dotted with mature trees. Concrete curbs line the north and west edges of the lot.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This grassy corner lot is vacant.





1. Survey number: JP-AS-006-214		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 311	Street (name): N. McKee Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1955	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input type="checkbox"/> C <input checked="" type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 6/6 vinyl sash
24. Vernacular or property type: Minimal Traditional	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style: Minimal Traditional	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): c.2010 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape L-shaped	33. Exterior wall cladding: Vinyl	
27. No. of stories: 1	34. Foundation material Stone	Endangered by:
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Side-gabled	36. Front porch type/placement: Stoop	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1960 city directory: Henry C. Jimmerson (Eva) - employee B.F. Goodrich Tire & Rubber.

This resource has poor integrity. Non-historic alterations compromise the ability of this resource to convey its historic function and date of construction. This resource would be non-contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. McKee Avenue to the west and is located in the east portion of the Survey Area. An ornamental lawn with mature trees characterizes the landscaping. A concrete walkway leads to the front porch and a non-historic wood fence encloses the rear of the lot. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This dwelling faces west and has an L-shaped footprint. It has a parged stone foundation and vinyl cladding. The side-gable roof has asphalt shingles. The dwelling is three bays wide and two bays deep. Singles and pairs of six-over-six vinyl windows occupy the north and south bays of the primary elevation while a non-historic wood door occupies the center bay. The roof slightly overhangs and shelters the north two bays and a concrete stoop.







1. Survey number: JP-AS-006-215		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 311	Street (name): N. Michigan Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 2004	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 6/6 vinyl sash
24. Vernacular or property type: Ranch	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape L-shaped	33. Exterior wall cladding: Vinyl	
27. No. of stories: 1	34. Foundation material CMU	
28. No. of bays (1st floor): 3	35. Basement type: Crawl Space	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Cross-gabled	36. Front porch type/placement: Recessed stoop	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually)		
<input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible		
<input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

This resource was constructed in 2004.

This resource is less than fifty years of age and is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This property occupies the southeast corner of the intersection of N. Michigan Avenue and E. North Street, facing west. A non-historic shed outbuilding with plywood sheet cladding and a gambrel roof is located southeast of the lot. It would be non-contributing to a potential historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Ranch dwelling faces west and has an L-shaped footprint. It has a concrete masonry unit foundation, vinyl cladding, and a side-gable roof with asphalt shingles. A cross-gable is located at the north end of the dwelling and houses an attached garage. The dwelling is four bays wide and one bay deep. The garage forms the first bay while six-over-six vinyl windows with false shutters occupy the third and fourth bays. The second bay is recessed and contains the primary entrance.









1. Survey number: JP-AS-006-216		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 312	Street (name): N. Mineral Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1900	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 6/6 vinyl sash
24. Vernacular or property type: Pyramid Square	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): c.2010 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape T-shaped	33. Exterior wall cladding: Hardboard, vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Stone	
28. No. of bays (1st floor): 3	35. Basement type: None	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Hipped	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: George F. Testerman (Edith, daughter Leta, son George), white, blacksmith at zinc mine, rents home; 1920 city directory: Frank H. Davis (Margaret) - carpenter; 1950 Sanborn: 1-story dwelling; 1960 city directory: Roy J. Warren (Jean - Joplin Cleaners).

This resource has poor integrity. Non-historic alterations to the siding, windows, and porch compromise the ability of this resource to convey its historic function and date of construction. It is not eligible or would not contribute to a potential historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Mineral Avenue to the east and is located in the west portion of the Survey Area. An ornamental lawn with mature trees characterizes the landscaping. A concrete sidewalk abuts the east edge of the property. A concrete walkway leads from the sidewalk to the front porch. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Pyramid Square Folk House faces east and has a T-shaped footprint. It has a stone foundation, asphalt shingle roof, and pressboard and vinyl cladding. The dwelling is three bays wide and three bays deep. A non-historic wood door occupies the center bay of the primary elevation while six-over-six vinyl windows occupy the remaining bays. A non-historic, three-quarter width open porch shelters the bays. It has a shed roof supported by wood posts and a concrete slab foundation.







1. Survey number: JP-AS-006-217		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 315	Street (name): N. Mineral Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1900	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement lower 1/1 wood, 6/6 vinyl sash
24. Vernacular or property type: American Foursquare	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): c.2010 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 2	34. Foundation material CMU	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Hipped	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: George Lurwick (Lula; daughters Ruth, Freda, Madeline, and Jeannette; sons Howard and George), white, machinist at zinc mine, owns home; 1920 city directory: Harry Jones (Nora) - foreman Union Depot; 1935 city directory: Same as 1940 Census; 1940 Census: Elmer W. Day (Nellie, sons Richard and Marvin), white, father is city fireman, son is tire repair and salesman, owns home, same 1935; 1950 Sanborn: 2-story dwelling; 1960 city directory: Marion W. Dial (Rozina) - principal Lincoln School.

This resource has poor integrity. Non-historic alterations compromise the ability of this resource to convey its historic function and date of construction. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Mineral Avenue to the west and is located in the west portion of the Survey Area. An ornamental lawn with mature trees characterizes the landscaping. A concrete sidewalk abuts the west edge of the property. A concrete walkway leads from the sidewalk to the front porch. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This two-story dwelling faces west and has a rectangular footprint. The dwelling has a concrete masonry unit foundation, vinyl cladding, and a hipped roof with asphalt shingles and a center gable at the primary elevation. The dwelling is three bays wide and three bays deep. A one-story hipped roof addition projects from the rear elevation and forms the third bay. One-over-one vinyl windows occupy the north and south first-story bays of the primary elevation and an entrance forms the center bay. The door was not visible at the time of survey. Six-over-six windows occupy both second-story bays at the primary elevation. A three-quarter width open porch shelters the primary elevation bays. It has a concrete foundation and hipped roof with asphalt shingles. Squared wood posts on concrete block piers support the porch roof.







1. Survey number: JP-AS-006-218		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 316	Street (name): N. Mineral Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1900	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 wood sash
24. Vernacular or property type: National Folk	31. Chimney placement: Center, exterior	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): c.2010 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Asbestos	Endangered by:
27. No. of stories: 1	34. Foundation material Stone	40. No. of outbuildings (describe in box 40 cont.): 1
28. No. of bays (1st floor): 2	35. Basement type: None	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>
29. Roof type: Cross-gabled	36. Front porch type/placement: Veranda, full-width	

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: James L. Kelly (Mary, sons James and Marvin, daughters Hanna, Rowena, Eulois), white; father is ore buyer, low grade; son is jig man at zinc mine; rents home; 1920 city directory: Benjamin F. Dunkle (Nola) - driller; 1950 Sanborn: 1-story dwelling; 1960 city directory: Robert S. Kingrey (Doris) - machinist Vicker's.

This resource has good integrity. It is not eligible because there is no concentration resources to constitute a historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Mineral Avenue to the east and is located in the west portion of the Survey Area. An ornamental lawn with mature trees characterizes the landscaping. A concrete sidewalk abuts the east edge of the property. A gravel drive leads to a garage outbuilding. A single-bay garage is located north of the dwelling. It has a concrete foundation, pressboard cladding, and a front-gable roof with asphalt shingles. A non-historic overhead garage door occupies the single bay. The date of construction is unknown. This garage has fair integrity. It is not eligible because there is no concentration resources to constitute a historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This National Folk House dwelling faces east and has a rectangular footprint. It has a stone foundation and cross-gabled roof with asphalt shingles and wood cladding in the gable peaks. The dwelling has asbestos shingle cladding. It is two bays wide and three asymmetrical bays deep. A non-historic wood door occupies the south bay of the primary elevation while a historic one-over-one wood window occupies the north bay. A shed-roof porch with a concrete foundation and non-historic decorative metal support posts spans the width of the primary elevation. Secondary entrances are located at the west elevations of the cross-gabled projections. The south secondary entrance contains a historic wood door with historic trim while the north secondary entrance contains a non-historic wood door with non-historic flat trim. A concrete masonry unit exterior chimney is located at the north elevation.





316





1. Survey number: JP-AS-006-219		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 323	Street (name): N. Mineral Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1900	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 wood sash
24. Vernacular or property type: Gabled-Ell	31. Chimney placement: Center, straddle ridge	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): c.1945 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Square	33. Exterior wall cladding: Asbestos	Endangered by:
27. No. of stories: 1	34. Foundation material Stone	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Cross-gabled	36. Front porch type/placement: Open, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1920 city directory: Richard Anderson (Dorothy) - foreman; 1935 city directory: Same as 1940 Census; 1940 Census: Dorothy Anderson, white, retired; Lula Turman (son Erwin Miller), white, unemployed 208 weeks; owns home, same 1935; 1950 Sanborn: 1-story dwelling; 1960 city directory: vacant.

This resource has good integrity. It is not eligible because there is no concentration resources to constitute a historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Mineral Avenue to the west and is located in the west portion of the Survey Area. An ornamental lawn with mature trees characterizes the landscaping. A concrete sidewalk abuts the north and west edges of the property and a chain-link fence encircles the lot. A concrete block garage outbuilding is located at the southwest corner of the lot. The historic garage has a front-gable roof with wood cladding in the peak. A pair of historic hinged wood doors occupies the single-bay. The garage good retains integrity. It is not eligible because there is no concentration resources to constitute a historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Gabled-Ell dwelling faces west and has a square footprint. It has stone foundation, asphalt roof, and asbestos shingle cladding. A brick straddle-ridge chimney pierces the roof. The dwelling is three bays wide and three bays deep. An enclosed shed-roof porch forms the fourth bay. A pair of historic one-over-one wood windows occupies the north bay of the primary elevation while single historic one-over-one wood windows occupy the remaining bays. The south two bays recede, creating a partial-width open porch. The porch has a shed roof, parged foundation, and turned wood support posts. An entrance is located in the north wall of the projecting ell at the west elevation. The dwelling's windows feature historic wood trim and modest crown molding.









1. Survey number: JP-AS-006-220		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 401	Street (name): N. Mineral Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1900	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 wood sash
24. Vernacular or property type: Pyramid Square	31. Chimney placement: Center, straddle ridge	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): Unknown <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Square	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Parged	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Truncated hip	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: Alma Cole - waitress; Ida Williamson - laundress at factory; white, rents home; 1920 city directory: vacant; 1920 Census: Charles Stone (Iola, son Leonard), African American, porter barber shop, rents home; 1935 city directory: Same as 1940 Census; 1940 Census: Mark Waterman (Geneva - cigar roller, son Don; mother-in-law Myrtle Ray - salesman), white, rents home, same 1935; 1950 Sanborn: 1-story dwelling; 1960 city directory: George West (Valeska) - machinist Vicker's.

This resource has fair integrity. Some non-historic alterations, including the application of non-historic siding, compromises its integrity slightly. However, this resource retains its historic form, porch, and windows, sufficient to communicate historic associations and date of construction. It is not eligible because there is no concentration of resources to constitute a historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Mineral Avenue to the west and is located in the west portion of the Survey Area. An ornamental lawn with mature trees characterizes the landscaping. A concrete sidewalk abuts the south and west edges of the property and a chain-link fence encircles the lot. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Pyramid Square Folk House faces west and has a square footprint. It has a parged foundation, asphalt shingle roof, and vinyl cladding. It is three bays wide and two bays deep. A brick chimney pierces the chimney peak. A wood door occupies the center bay of the primary elevation while narrow one-over-one wood windows fill the remaining bays. An open, three-quarter width porch shelters the bays. It has a shed roof, concrete foundation, and squared wood support posts.







1. Survey number: JP-AS-006-221		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 402	Street (name): N. Mineral Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1920	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 wood sash
24. Vernacular or property type: Bungalow/Bungaloid	31. Chimney placement: Center, rear slope	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Wood	Endangered by:
27. No. of stories: 1.5	34. Foundation material CMU	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Hipped	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1920 city directory: William Kee - blacksmith; Eugene Kee, Norman & Maude Kee; 1940 Census: Arthur Langhrey (Forest, daughters Maxine and Melba), white, miner, unemployed 14 weeks, rents home, El Dorado MO 1935; 1950 Sanborn: 1-story dwelling; 1960 city directory: Mrs. Izzie Lazenby.

This resource has good integrity. It is not eligible because there is no concentration of resources to constitute a historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Mineral Avenue to the east and is located in the west portion of the Survey Area. An ornamental lawn with mature trees characterizes the landscaping. A concrete sidewalk abuts the south and east edges of the property. A low concrete retaining wall lines the east and south edges and a chain-link fence encircles the lot. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This bungalow dwelling faces east and has a rectangular footprint. It has a concrete block foundation, wood clapboard cladding, and an asphalt shingle roof. Hipped roof dormers are located on the south and east slopes while a short brick chimney pierces the west slope. The dwelling is three bays wide and four bays deep. An enclosed shed-roof porch forms the fourth bay. Historic one-over-one wood windows occupy the north and south bays of the primary elevation while a wood door with glazing occupies the center bay. An open, three-quarter width porch shelters the bays. It has a shallow hipped roof, concrete foundation, and wood support posts. The dormers and secondary elevations possess historic one-over-one wood windows and the secondary elevation windows have modest crown molding.

al Ave







1. Survey number: JP-AS-006-222		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address V37 - 400 block	Street (name): N. Mineral Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Vacant/Not in Use

HISTORICAL INFORMATION

12. Construction date: 2000	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input type="checkbox"/> building <input checked="" type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: N/A	37. Windows: <input type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement N/A
24. Vernacular or property type: Vacant Lot	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: N/A	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape N/A	33. Exterior wall cladding: N/A	Endangered by:
27. No. of stories: N/A	34. Foundation material N/A	
28. No. of bays (1st floor):	35. Basement type: N/A	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: N/A	36. Front porch type/placement: N/A	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

The resources historically constructed on this lot were demolished c.2000. It remains vacant.

This resource has poor integrity due to the demolition of buildings previously constructed on the lot. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot occupies the middle of the 400 block on the east side of N. Mineral Ave. at the west end of the Survey Area. Concrete sidewalks abut the west side of the lot.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This grassy lot is vacant.





1. Survey number: JP-AS-006-223		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 406	Street (name): N. Mineral Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1905	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 wood sash
24. Vernacular or property type: Gabled-Ell	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): c.1980 <input checked="" type="checkbox"/> Altered Date(s): c.2000 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape L-shaped	33. Exterior wall cladding: Brick, vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Stone	
28. No. of bays (1st floor): 2	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Cross-gabled	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: Clark Luper (Tillie; sons Ray, William, and Hubert; daughter Mary) - retail merchant, grocery; brother Joseph A. Luper - engineer, zinc mine; owns home; 1920 city directory: Thomas J. Carney (Nettie) - fireman; 1935 city directory: Same as 1940 Census; 1940 Census: Helen Carroll (sons Billy and Harold; daughters Dorothy and Catherine), white, rents home, same 1935; Ella Friend, white, seamstress, unemployed 136 weeks, rents home, same 1935; 1950 Sanborn: 1-story dwelling; 1960 city directory: Mrs. Beulah Curtis - widow; Edna Hall - maid.

This resource has poor integrity due to non-historic alterations of the siding, windows, and porch. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Mineral Avenue to the east and is located in the west portion of the Survey Area. An ornamental lawn with mature trees characterizes the landscaping. A concrete sidewalk abuts the east edge of the property. A low concrete retaining wall with concrete steps lines the east edge of the lot. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Gabled-Ell dwelling faces east and has a rectangular footprint. It has a stone foundation and complex asphalt shingle roof. Brick veneer clads the lower quarter of the primary elevation gabled-ell while vinyl clads the remainder of the dwelling. The dwelling is two asymmetrical bays wide and four bays deep. An enclosed shed-roof porch forms the fourth bay. One-over-one wood windows occupy the primary elevation bays. The primary entrance features a non-historic wood door and curved brick steps and is located in the south wall of the gabled-ell. A non-historic shed-roof porch shelters the entrance and south bay. It has a concrete slab foundation and decorative metal support posts. A secondary entrance with a concrete stoop is located at south elevation.







1. Survey number: JP-AS-006-224		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 411	Street (name): N. Mineral Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1910	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 4/4 vinyl sash
24. Vernacular or property type: National Folk	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): c.2000 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Metal	Endangered by:
27. No. of stories: 1.5	34. Foundation material Stone	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Saltbox	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: Ella Elwood (daughter Pearl), white, both are laundresses, rents home; 1920 city directory: Luther Anderson (Laura); Richard Anderson - shining parlor; 1920 Census: Mulatto, rents; 1935 city directory: Same as 1940 Census; 1940 Census: L.F. Clements (Beulah, sons Billy, Bobbie, Charles, Nelson, Carl, Rex; daughter Mary Louise), white, laborer, rents home, same 1935; 1950 Sanborn: 1.5-story dwelling; 1960 city directory: Frank J. Ackerson (Pauline).

This resource has fair integrity. It retains its historic form and porch, sufficient to communicate its historic associations and date of construction. It is not eligible because there is no concentration of resources to constitute a historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Mineral Avenue to the west and is located in the west portion of the Survey Area. It has a narrow setback and an ornamental lawn characterizes the landscaping. A concrete sidewalk abuts the west edge of the property. No outbuildings were observed

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This dwelling faces west and has a rectangular footprint. It has a stone foundation, metal cladding, and asphalt shingle roof. It is three bays wide. A non-historic wood door occupies the center bay while four-over-four vinyl windows occupy the remaining bays. Four-over-four vinyl windows are located in the gable peaks and are the only windows at the north and south elevations. An open, three-quarter width porch shelters the primary elevation bays. It has a shed roof and concrete foundation. Wood columns on brick piers support the porch roof.







1. Survey number: JP-AS-006-225		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 414	Street (name): N. Mineral Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1920	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Minimal Traditional	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style: Minimal Traditional	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): Unknown <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Irregular	33. Exterior wall cladding: Brick, vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 4	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Cross-gabled	36. Front porch type/placement: Portico	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1960 city directory: Herbert DeVaughn (Iva) - yard worker.

This resource has poor integrity due to the alterations to the siding and roof height. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Mineral Avenue to the east and is located in the west portion of the Survey Area. An ornamental lawn characterizes the landscaping. A concrete sidewalk abuts the east edge of the property while an east-west gravel alley abuts the north edge. A low concrete retaining wall abuts the sidewalk. A modern frame carport with attached shed is located south of the dwelling. It is not eligible.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Minimal Traditional dwelling faces east and has an irregular footprint. It has a concrete foundation and asphalt shingle roof. The primary elevation has a combination of brick and vinyl cladding. The secondary elevations have vinyl cladding. The dwelling is four bays wide and three bays deep. One-over-one vinyl windows occupy the first and third bays while a vinyl tripartite picture fills the fourth bay. A wood panel door defines the second bay. A front-gable porch shelters the entrance. It has a concrete foundation and steps. Squared wood columns on concrete piers support the porch roof. A secondary entrance is located at the south elevation. A shed-roof porch with brick walls shelters this entrance. The roof above the south wing has been raised above its original height.









1. Survey number: JP-AS-006-226		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address V38 - 500 block	Street (name): N. Mineral Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Vacant/Not in Use

HISTORICAL INFORMATION

12. Construction date: 2000	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input type="checkbox"/> building <input checked="" type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: N/A	37. Windows: <input type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement N/A
24. Vernacular or property type: Vacant Lot	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: N/A	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape N/A	33. Exterior wall cladding: N/A	Endangered by:
27. No. of stories: N/A	34. Foundation material N/A	
28. No. of bays (1st floor):	35. Basement type: N/A	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: N/A	36. Front porch type/placement: N/A	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

The resources historically constructed on this lot were demolished c.2000. It remains vacant.

This resource has poor integrity due to the demolition of buildings previously constructed on the lot. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Mineral Avenue to the east and is located in the west portion of the Survey Area. An ornamental lawn characterizes the landscaping. A concrete sidewalk abuts the east edge of the property while an east-west gravel alley abuts the north edge. A low concrete retaining wall abuts the sidewalk. It is not eligible.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This grassy lot is vacant. A low, stone retaining wall with steps lines the east edge of the lot.

E. Wilson St
S Mineral Ave





1. Survey number: JP-AS-006-227		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 505	Street (name): N. Mineral Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1930	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Ranch	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Metal	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 4	35. Basement type: None	40. No. of outbuildings (describe in box 40 cont.): 2
29. Roof type: Side-gabled	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1960 city directory: Kenneth K. Newman (Mary).

This resource has good integrity. It is not eligible because there is no concentration resources to constitute a historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Mineral Avenue to the west and is located in the west portion of the Survey Area. An ornamental lawn characterizes the landscaping. A concrete sidewalk abuts the west edge of the property. A modern metal carport is located south of the dwelling. Two shed outbuildings are located near the southeast corner of the dwelling. A side-gabled shed with exposed rafter tails, wide-profile wood cladding, and a wood door is perpendicular to a front-gabled shed with wood panel cladding and paired wood doors. The dates of construction are unknown. These outbuildings are not eligible.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Ranch dwelling faces south and has a rectangular footprint. It has a concrete foundation and metal siding. The front-gable roof has asphalt shingles. The dwelling is four bays wide and one bay deep. A non-historic wood door occupies the first bay. Single one-over-one window vinyl windows occupy the second and third bay while a pair of one-over-one vinyl windows defines the fourth bay. A shed-roof porch shelters the entrance and features a concrete foundation and non-historic decorative metal support posts. A non-historic concrete slab porch spans the rest of the primary elevation.





505

505







1. Survey number: JP-AS-006-228		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 511	Street (name): N. Mineral Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1979	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Ranch	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape L-shaped	33. Exterior wall cladding: Hardboard	
27. No. of stories: 1	34. Foundation material CMU	Endangered by:
28. No. of bays (1st floor): 3	35. Basement type: Crawl Space	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Side-gabled	36. Front porch type/placement: Portico	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

This resource was constructed in 1979.

This resource is less than fifty years of age and it does not exhibit exception significance necessary to merit individual listing the National Register. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Mineral Avenue to the west and is located in the west portion of the Survey Area. An ornamental lawn with mature trees and shrubs characterizes the landscaping. A concrete sidewalk abuts the west edge of the property while a north-south gravel alley abuts the east edge. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Ranch dwelling faces west and has an L-shaped footprint. It has a concrete masonry unit foundation and an asphalt shingle roof. Brick veneer clads the lower third of the primary elevation and the remaining of the cladding is pressboard. The dwelling is three bays wide and four bays deep. A non-historic wood door with glazing occupies the center bay while a one-over-one vinyl windows occupies the south bay. The north bay contains a one-by-one wood window. A non-historic porch with a concrete foundation, front-gable roof, and decorative metal support posts shelters the entrance bay.







1. Survey number: JP-AS-006-229		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 512	Street (name): N. Mineral Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1890	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: National Folk	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): Unknown <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Not Visible	40. No. of outbuildings (describe in box 40 cont.): 0
28. No. of bays (1st floor): 3	35. Basement type: Unknown	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>
29. Roof type: Side-gabled	36. Front porch type/placement: Portico	

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: William Brown (Nellie, daughters Nellie and Beulah), white, father is laborer at tailing mill, oldest daughter is waiter at restaurant, rents home; 1920 city directory: Mrs. S.A. Fields; 1935 city directory: Same as 1940 Census; 1940 Census: Edward Fields, white, retired, owns home, same 1935; 1950 Sanborn: 1-story dwelling; 1960 city directory: Fred I. Robinson (Kathlene).

This resource has poor integrity. Non-historic alterations compromise the ability of this resource to convey its historic function and date of construction. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Mineral Avenue to the east and is located in the west portion of the Survey Area. An ornamental lawn with mature trees and shrubs characterizes the landscaping. A concrete sidewalk abuts the east edge of the property while a north-south gravel alley abuts the west edge. A low concrete retaining wall abuts the sidewalk. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This National Folk House dwelling faces east and has a rectangular footprint. It has an asphalt roof and metal cladding. The foundation is not visible. The dwelling is three bays wide and three bays deep. An enclosed shed-roof porch at the west elevation forms the third bay. An enclosed shed-roof porch contains the primary elevation bays. The porch enclosure is an alteration. A non-historic wood door occupies the center bay while a one-over-one vinyl window occupies the north bay. A vinyl tripartite picture window defines the south bay. A non-historic flat-roof porch with a concrete foundation, wood support posts, and a metal railing shelters the entrance







1. Survey number: JP-AS-006-230		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 515	Street (name): N. Mineral Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1910	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Pyramid Square	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): c.2000 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Parged	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Hipped	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: Manley Y. Campbell (Annie, sons Arthur, Lennie, Earl, Galen), white, motor man street car, rents home; 1920 city directory: Joseph Martin (Fronia) - miner; 1935 city directory: Same as 1940 Census; 1940 Census: Grace Ryles (daughters Louise and Allene, son Otatis) white, housewife, owns home, same 1935; 1950 Sanborn: 1-story dwelling; 1960 city directory: James R. Jones (Lois) - driver Griffin Wholesale Grocer.

This resource has poor integrity. Non-historic alterations, including the installation of not-historic siding, windows, and porch supports. It does not compromise the ability of this resource to convey its historic function and date of construction. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Mineral Avenue to the west and is located in the west portion of the Survey Area. An ornamental lawn with mature trees and shrubs characterizes the landscaping. A concrete sidewalk abuts the west edge of the property while a north-south gravel alley abuts the east edge. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Pyramid Square Folk House faces west and has a rectangular footprint. The foundation is parged and the pyramidal hipped roof features asphalt shingles and narrow eaves. The dwelling has vinyl cladding. It is three bays wide and two bays deep. A non-historic wood door occupies the center bay while one-over-one wood windows define the remaining bays. A shed-roof porch with a concrete foundation and decorative metal support posts shelters the primary elevation bays.







1. Survey number: JP-AS-006-231		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 520	Street (name): N. Mineral Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1886	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 wood sash
24. Vernacular or property type: American Foursquare	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): Unknown <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Square	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 2	34. Foundation material Stone	
28. No. of bays (1st floor): 5	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Gable-on-hip	36. Front porch type/placement: Recessed, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: William K. Dalton (Amanda, sons Frank, Roy, Earnest, and daughter Ruth), white, real estate agent, owns home; 1920 city directory: James Mayberry (Amanda) - laborer; Henry Mayberry - employee Concrete & Steel Construction Co.; 1935 city directory: Same as 1940 Census; 1940 Census: Nelson Lundstrum (Addie, sons Nelson Jr., Thomas, John, Paul; daughters Helen (house maid), Jacque, Addie Marie, Mary, Jane), white, electric refrigerator mechanic, owns home, same 1935, wife's family rural 1935; Fannie Willis, white, retired, rents flat, same 1935; John Garrett (Jennie, daughters Frances, Rosalee, Loretha), white, laborer, unemployed 60 months, rents flat, same 1935; 1950 Sanborn: 2-story dwelling; 1960 city directory: Arthur L. Watson (Mary) - driver Ray & Co. Transports.

This resource has fair integrity. It retains its historic form and alterations It is not eligible. However, there is no concentration of resources to constitute a historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Mineral Avenue to the east and is located in the west portion of the Survey Area. An ornamental lawn with mature trees and shrubs characterizes the landscaping. A concrete sidewalk abuts the east edge of the property while a north-south gravel alley abuts the west edge. A gabled garage outbuilding is located in the northwest corner of the lot and fronts E. Persimmon Street to the north. It has a seamed metal roof and vinyl cladding. A set of paired vinyl-clad doors occupies the vehicular bay at the primary elevation while wood pedestrian door is in the south end of the east elevation. The loss of historic materials compromises the integrity of the garage. It has poor integrity. It is not eligible.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This two-story American Foursquare dwelling faces west and has a square footprint. It has a stone foundation and vinyl cladding. The hipped roof with gablet has asphalt shingles. A one-story shed-roof addition projects from the south elevation. The dwelling is five asymmetrical bays wide at the first story and two asymmetrical bays wide at the second story. It is two bays deep. A non-historic wood door with glazing occupies the center bay while one-over-one wood windows occupy the first, second, and fourth bays. A wood tripartite picture window defines the fifth bay, which projects from the elevation. A shed-roof porch with a concrete foundation and squared wood support posts shelters the second-fourth bays. One-over-one wood windows occupy the second-story bays.











1. Survey number: JP-AS-006-232		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 523	Street (name): N. Mineral Avenue
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1974	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Ranch	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): Unknown <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Brick, vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 5	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Side-gabled	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

This resource was constructed in

This resource is less than fifty years of age and it does not exhibit exception significance necessary to merit individual listing the National Register. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts N. Mineral Avenue to the west and is located in the west portion of the Survey Area. An ornamental lawn with mature trees and shrubs characterizes the landscaping. A concrete sidewalk abuts the west edge of the property while a north-south gravel alley abuts the east edge. A modern shed outbuilding with a front-gable roof and wood cladding is located in the northeast corner of the lot. It is not eligible.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Ranch dwelling faces west and has a rectangular footprint. It has a concrete foundation and asphalt roof. Brick veneer clads the lower third of the dwelling and the north half of the primary elevation. The dwelling is five bays wide and two bays deep. An overhead garage door occupies the north bay while an entrance with a metal storm door occupies the center bay. One-over-one vinyl windows occupy the remaining bays. A shed-roof porch shelters the north three bays.



1FR-655









1. Survey number: JP-AS-006-233		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 500	Street (name): N. Murphy Boulevard
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Public		11a. Historic use (if known): Recreation and Culture/Outdoor Recreation	11b. Current use: Recreation and Culture/Outdoor Recreation

HISTORICAL INFORMATION

12. Construction date: 1906-1912; 1928	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1906-1912; 1928, 1933	16. Builder/contractor: WPA	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Criterion C - Landscape Architecture	17. Original or significant owner: William H. Landreth	20. National Register eligible? <input checked="" type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input type="checkbox"/> building <input checked="" type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: N/A	37. Windows: <input type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement N/A
24. Vernacular or property type:	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: N/A	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): c. 1980, c. 2005 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape N/A	33. Exterior wall cladding: N/A	Endangered by:
27. No. of stories: N/A	34. Foundation material N/A	
28. No. of bays (1st floor):	35. Basement type: N/A	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: N/A	36. Front porch type/placement: N/A	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

Over the course of four years between 1906 and 1910, individuals and companies donated lots to the City for use as a public park. Donors of the initial fifteen acres included William and Catherine Leckie, James J. Cox, Picher Lead Company, and Mr and Mrs. Charles Barrett. The East Joplin Improvement Association enlarged the park to twenty acres in 1912. The park continued to grow. By 1926, the park had picnic grounds, a playground, a rustic stone bridge, flower gardens, a bandstand, a refreshment stand, a swimming pool, and a bathhouse. In 1928, William H. Landreth, civic leader and owner of the Landreth Machinery Company, donated one hundred acres to the City to combine with Mineral Park to create Landreth Park. Beginning in 1933, WPA projects vastly improved the park. Over one thousand men were hired for grading, building stone gateways, and paving the roads through the park.

This park retains good integrity to convey its history and significance for its associations with the early history of Joplin, the New Deal Era improvements, and the landscape design. It is potentially eligible for individual listing in the National Register under Criterion C for Landscape Architecture.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950. Gibbons, Charles. Angling in the Archives. Joplin MO: H. Lang Rogers, 1996; Livingston Joel T., A History of Jasper County Missouri and Its People. Chicago: Lewis Publishing, 1912.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

Landreth Park is located in the northwest corner of the Survey Area. Landreth Park is bordered to the east and west by residential neighborhoods. A college complex abuts the park to the north and a commercial area is located to the south. Northwest Murphy Boulevard, a main city thoroughfare, runs north-south through the west third of the park.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

Landreth Park is a public park roughly bounded by East Hill Street to the south, North Landreth Avenue at the east and north. Joplin Creek and the Kansas City Southern Railroad tracks form the west boundary. The park is characterized by grassy open areas with mature trees, recreation fields, and walking trails. A northwest-southeast concrete storm culvert with stone retaining walls roughly bisects the park. The historic baseball fields are extant on the west side the park. The swimming pool, bath house, and bandstand have been demolished on the east side of the park (between 1961 and 1996), but the historic rustic stone bridge is extant. Non-historic structures and buildings are consistent with the historic use of the park, specifically restrooms, picnic shelters, and an amphitheater (constructed around 2005).



JOPLIN
GOLF COURSE

Established in 1926, Joplin Golf Course is a 36-hole, championship course designed by Alister MacKenzie. The course is known for its challenging layout and beautiful scenery. It is a member of the United States Golf Association (USGA) and is open to all players.

For more information, please contact the clubhouse at 417-863-9122.

Hours of operation: 7:00 AM - 6:00 PM, Monday - Friday
8:00 AM - 6:00 PM, Saturday & Sunday

Reservations for all Park Events at JGC















































HISTORIC
Saylor
Lead Discovered,
Shaft of Moffet
& Sergeant



















































1. Survey number: JP-AS-006-234		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1001	Street (name): N. Murphy Boulevard
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Public		11a. Historic use (if known): Defense/Military Facility	11b. Current use: Defense/Military Facility

HISTORICAL INFORMATION

12. Construction date: 1955	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Metal	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement multi-light fixed
24. Vernacular or property type: Other Vernacular	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Masonry	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): c.1995 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Irregular	33. Exterior wall cladding: Brick	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 5	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Hipped	36. Front porch type/placement: N/A	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1960 city directory: United States Army Training Center.

This resource has fair integrity. The non-historic hipped roofs change the mid-century appearance of the building. However, it continues to communicate its association with the secret. It is not eligible because there is no concentration of resources to constitute a historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot is located in the northwest corner of the Survey Area and is within the boundary of Landreth Park. It has a deep setback and is heavily fenced. A paved drive leads from Northwest Murphy Boulevard to the Reserve Center complex. Paved parking lots abut the drive to the north and south. Paved parking lots abut the building. Two outbuildings are located east of the building. A modern corrugated metal garage with a side-gable roof abuts a historic brick garage. The historic garage is two bays wide. Metal overhead garage doors occupy the primary elevation bays. Five-light clerestory windows with concrete or stone sills line the east elevation and are separated by brick pilasters. The historic garage retains good integrity. It is not eligible because there is no concentration of resources to constitute a historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

The Army Reserve Center faces southwest and has an irregular footprint comprised of two main blocks connected by a short wing. It has a deep set-back and is heavily fenced. It has a concrete foundation and brick cladding. The south block has a metal side-gable roof with an intersecting hipped-roof block at the east end. The hipped block rises slightly above the side-gable block. The south block is approximately sixteen bays. The fourth through seventh-from-east primary elevation bays recede, creating a partial-width porch. An entrance occupies the fourth-from-east bay. Two-over-two windows occupy the remaining porch bays. Small, rectangular windows occupy the remaining primary elevation bays. The south block is two bays. Six-light fixed sash windows occupy the bays. The north block has a metal hipped-roof and rises above the south block. The north block is four bays. A vehicular bay with a metal door occupies the second bay while six light metal clerestory windows define the remaining bays. An entrance is located below the last (north) window bay. A metal shed-roof addition projects from the NW elevation. The addition is four asymmetrical bays. Metal doors with glazing occupy the center two bays while single one-over-one metal windows occupy the end bays. A shed roof shelters the entrances.















1. Survey number: JP-AS-006-235		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 902	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1905	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 wood sash
24. Vernacular or property type: National Folk	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): Unknown <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Metal	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Side-gabled	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: James M. Longan (Carrie; sons Frank, Clifton, Artie, Mountain; daughter Gladys; cousin Jacob); white; father is miner, son is public works laborer, cousin is lawyer; rents home; 1920 city directory: Lenoard Coker (Irene) - laborer; 1935 city directory: Same as 1940 Census; 1940 Census: Harold E. Wetherell (Kathleen, son Daniel Lee, brother-in-law Joseph McGee), white, printer, rents home, same 1935; 1950 Sanborn: 1-story dwelling; 1960 city directory: Lloyd Wallace (Laura) - custodian First National Bank.

This resource has poor integrity. Non-historic alterations to the siding, replacement of doors, and replacene compromise the ability of this resource to convey its historic function and date of construction. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts E. North Street to the north and is located in the north portion of the Survey Area. An ornamental lawn with mature trees and shrubs characterizes the landscaping. A concrete sidewalk abuts the north and west edges of the property while an east-west gravel alley abuts the south edge. A modern corrugated metal shed is located southeast of the dwelling. It would be non-contributing to a potential historic district. A historic outbuilding is located south of the dwelling. It has a rectangular footprint and side-gable roof. The outbuilding has a concrete masonry unit foundation and a combination of wood and metal cladding. It is one bay wide and one bay deep. A historic wood door is located at the north elevation and is sheltered by a non-historic shed-roof porch. A historic one-over-one wood window occupies the single west elevation bay. It retains fair integrity but it is not eligible because there is no concentration of resources to constitute a historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This National Folk House dwelling faces north and has a rectangular footprint. It has a concrete foundation, asphalt shingle roof, and metal cladding. The dwelling is three bays wide and two bays deep. Enclosed shed-roof porches at the east and west elevations form the contain the rear bays. The porch enclosure is an alteration. A non-historic three-quarter width porch shelters the primary elevation bays. A non-historic wood door with nine-light glazing occupies the center bay while one-over-one wood windows occupy the remaining bays.



1902







1. Survey number: JP-AS-006-236		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 903	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1915	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Pyramid Square	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): c.1980 <input checked="" type="checkbox"/> Altered Date(s): c.2000 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Hipped with lower cross-gable	36. Front porch type/placement: Portico	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: John M. Farris (Florence), white, fare man, zinc mine, owns home; 1920 city directory: vacant; 1920 Census: George Lindsay, African American, saloon keeper, rents home; 1950 Sanborn: 1-story dwelling; 1960 city directory: vacant.

This resource has poor integrity. Non-historic alterations to the siding, windows, door, and porch compromise the ability of this resource to convey its historic function and date of construction. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts E. North Street to the south and is located in the north portion of the Survey Area. An ornamental lawn with mature trees and shrubs characterizes the landscaping. A concrete sidewalk abuts the south and west edges of the property. A low, concrete retaining wall abuts the sidewalk at the south edge of the lot. A garage outbuilding is located in the northwest corner of the lot. It has pressboard cladding and a side-gabled roof with asphalt shingles. It is two bays wide. A one-by-one sliding window with flat board trim occupies the west bay while a set of non-historic wood doors occupies the east bay. A hipped roof vent pierces the center of the roof. The garage retains fair integrity. It is not eligible because there is no concentration resources to constitute a historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Pyramid Square dwelling faces south and has a rectangular footprint. It has concrete foundation and vinyl cladding. The hipped roof with cross gables has asphalt shingles. The dwelling is three bays wide and three asymmetrical bays deep. A non-historic wood door with nine-light glazing occupies the center bay of the primary elevation while paired one-over-one vinyl windows occupy the remaining bays. A front-gable roof with vinyl-wrapped knee brackets shelters the concrete stoop.



Call
Burd
RE/MAX







1. Survey number: JP-AS-006-237		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address v39 - 900 block	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Vacant/Not in Use

HISTORICAL INFORMATION

12. Construction date: 1980	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input type="checkbox"/> building <input checked="" type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: N/A	37. Windows: <input type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement N/A
24. Vernacular or property type: Vacant Lot	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: N/A	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape N/A	33. Exterior wall cladding: N/A	Endangered by:
27. No. of stories: N/A	34. Foundation material N/A	
28. No. of bays (1st floor):	35. Basement type: N/A	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: N/A	36. Front porch type/placement: N/A	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district	Other:	
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

The resources historically constructed on this lot were demolished c.1980. It remains vacant.

This resource has poor integrity due to the demolition of buildings previously constructed on the lot. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts E. North Street to the south and is located in the north portion of the Survey Area.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

The primary resource of this lot has been demolished. A side-gable outbuilding is located in the northwest corner of the lot. It has pressboard cladding and the foundation is not visible. It has poor integrity and is not eligible for listing.







1. Survey number: JP-AS-006-238		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 932	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Landscape/Parking Lot	11b. Current use: Landscape/Parking Lot

HISTORICAL INFORMATION

12. Construction date: 2008	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input type="checkbox"/> building <input type="checkbox"/> site <input checked="" type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: N/A	37. Windows: <input type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement N/A
24. Vernacular or property type:	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: N/A	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape N/A	33. Exterior wall cladding: N/A	Endangered by:
27. No. of stories: N/A	34. Foundation material N/A	
28. No. of bays (1st floor):	35. Basement type: N/A	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: N/A	36. Front porch type/placement: N/A	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

The resources historically constructed on this lot were demolished c.1980. When the tracks of the old St. Louis and San Francisco Railroad was converted to a four-mile hiking, running, and biking trail in c.2008, this lot was paved as a parking lot for the trailhead.

This resource is less than fifty years of age. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts E. North Street to the south and is located in the north portion of the Survey Area.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This is a c.2008 paved parking lot striped for thirty-six cars.





1. Survey number: JP-AS-006-239		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address V40 - 1000 block	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Vacant/Not in Use

HISTORICAL INFORMATION

12. Construction date: 1980	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input type="checkbox"/> building <input checked="" type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: N/A	37. Windows: <input type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement N/A
24. Vernacular or property type: Vacant Lot	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: N/A	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape N/A	33. Exterior wall cladding: N/A	Endangered by:
27. No. of stories: N/A	34. Foundation material N/A	
28. No. of bays (1st floor):	35. Basement type: N/A	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: N/A	36. Front porch type/placement: N/A	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

The resources historically constructed on this lot were demolished c.1980. It remains vacant.

This resource has poor integrity due to the demolition of buildings previously constructed on the lot. It is not eligible or would not contribute to a potential historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts E. North Street to the north and is located in the north portion of the Survey Area.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This grassy lot is vacant.





1. Survey number: JP-AS-006-240		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address V41 - 1000 block	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Vacant/Not in Use

HISTORICAL INFORMATION

12. Construction date: 1980	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input type="checkbox"/> building <input checked="" type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: N/A	37. Windows: <input type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement N/A
24. Vernacular or property type: Vacant Lot	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: N/A	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape N/A	33. Exterior wall cladding: N/A	Endangered by:
27. No. of stories: N/A	34. Foundation material N/A	
28. No. of bays (1st floor):	35. Basement type: N/A	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: N/A	36. Front porch type/placement: N/A	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

The resources historically constructed on this lot were demolished c.1980. It remains vacant.

This resource has poor integrity due to the demolition of buildings previously constructed on the lot. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts E. North Street to the south and is located in the north portion of the Survey Area.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This grassy lot is vacant.

RAISING
CROSSING
ROAD

RAISING
CROSSING
ROAD





1. Survey number: JP-AS-006-241		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1014	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1999	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Open Gable/Gambrel Front	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material CMU	
28. No. of bays (1st floor): 3	35. Basement type: Crawl Space	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Front-gabled	36. Front porch type/placement: Portico	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

This resource was constructed in 1999.

This resource is less than fifty years of age and it does not exhibit exception significance necessary to merit individual listing the National Register. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts E. North Street to the north and is located in the north portion of the Survey Area. An ornamental lawn with mature trees and shrubs characterizes the landscaping. A concrete sidewalk abuts the north edge of the property. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Open Gable dwelling faces north and has a rectangular footprint. It has a concrete masonry unit foundation and vinyl cladding. The front-gable roof has asphalt shingles. The dwelling is three bays wide and three bays deep. A non-historic fiberglass door occupies the center bay of the primary elevation while one-over-one vinyl windows occupy the remaining bays. A non-historic front-gable roof with vinyl knee brackets shelters the entrance and non-historic wood stoop. A secondary entrance occupies the center bay of the west elevation. This dwelling is a twin to the adjacent dwelling, 1020 E. North Street.







1. Survey number: JP-AS-006-242		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1020	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1999	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Open Gable/Gambrel Front	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material CMU	
28. No. of bays (1st floor): 3	35. Basement type: Crawl Space	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Front-gabled	36. Front porch type/placement: Portico	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018 45. Photographer: Brad Finch, f-stop Photography
----------------------------	--	---

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		Other:

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

This resource was constructed in 1999.

This resource is less than fifty years of age and it does not exhibit exception significance necessary to merit individual listing the National Register. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts E. North Street to the north and is located in the north portion of the Survey Area. An ornamental lawn with mature trees and shrubs characterizes the landscaping. A concrete sidewalk abuts the north edge of the property. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Open Gable dwelling faces north and has a rectangular footprint. It has a concrete masonry unit foundation and vinyl cladding. The front-gable roof has asphalt shingles. The dwelling is three bays wide and three bays deep. A non-historic fiberglass door occupies the center bay of the primary elevation while one-over-one vinyl windows occupy the remaining bays. A non-historic front-gable roof with vinyl knee brackets shelters the entrance and non-historic wood stoop. A secondary entrance occupies the center bay of the west elevation. This dwelling is a twin to the adjacent dwellings, 1014 and 1022 E. North Street.



7020



1020



1. Survey number: JP-AS-006-243		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1022	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1999	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Open Gable/Gambrel Front	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material CMU	
28. No. of bays (1st floor): 3	35. Basement type: Crawl Space	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Front-gabled	36. Front porch type/placement: Portico	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

This resource was constructed in 1999.

This resource is less than fifty years of age and it does not exhibit exception significance necessary to merit individual listing the National Register. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts E. North Street to the north and is located in the north portion of the Survey Area. An ornamental lawn with mature trees and shrubs characterizes the landscaping. A concrete sidewalk abuts the north edge of the property. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Open Gable dwelling faces north and has a rectangular footprint. It has a concrete masonry unit foundation and vinyl cladding. The front-gable roof has asphalt shingles. The dwelling is three bays wide and three bays deep. A non-historic fiberglass door occupies the center bay of the primary elevation while one-over-one vinyl windows occupy the remaining bays. A non-historic front-gable roof with vinyl knee brackets shelters the entrance and non-historic wood stoop. A secondary entrance occupies the center bay of the west elevation. This dwelling is a twin to the adjacent dwelling, 1020 E. North Street.



1022





1. Survey number: JP-AS-006-244		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1023	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1975	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 metal sash
24. Vernacular or property type: Ranch	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Brick, vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 4	35. Basement type: None	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Side-gabled	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

This resource was constructed in 1975.

This resource is less than fifty years of age and it does not exhibit exception significance necessary to merit individual listing the National Register. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling faces south and is in the north portion of the Survey Area. A concrete sidewalk abuts the south edge of the property. A concrete driveway leads to the carport. The lot features a large ornamental lawn. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Ranch dwelling faces south and has a rectangular footprint. It has a concrete foundation and side-gable roof with asphalt shingles. Brick veneer clads the lower third of the dwelling while the remainder is vinyl clad. The dwelling is four bays wide and three bays deep. A front-gable porch shelters the two east bays of the primary elevation. A wood door with metal storm door fills the second-from-east bay. One-over-one metal windows with false shutters define the remaining bays. A side-gable carport projects from the east elevation and shelters a secondary entrance. An enclosed storage area with gable roof is located at the east end of the carport.







1. Survey number: JP-AS-006-245		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1024	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 2008	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 4/4, 6/6 vinyl sash
24. Vernacular or property type: Open Gable/Gambrel Front	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Stucco	Endangered by:
27. No. of stories: 1	34. Foundation material CMU	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Front-gabled	36. Front porch type/placement: Portico	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

This resource was constructed in 2008.

This resource is less than fifty years of age and it does not exhibit exception significance necessary to merit individual listing the National Register. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

This lot fronts E. North Street to the north and is located in the north portion of the Survey Area. An ornamental lawn with mature trees and shrubs characterizes the landscaping. A concrete sidewalk abuts the north and east edges of the property. A shed outbuilding with a front-gable asphalt roof and concrete foundation is located behind the dwelling. It has pressboard cladding and a fiberboard door. It is not eligible.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Open Gable dwelling faces north and has a rectangular footprint. It has a concrete masonry unit foundation and stucco cladding. The front-gable roof has asphalt shingles. The dwelling is three bays wide and three bays deep. A non-historic wood door with nine-light glazing occupies the center bay of the primary elevation while six-over-six vinyl windows occupy the remaining bays. A non-historic front-gable roof with knee brackets shelters the entrance and concrete stoop.





1024





1. Survey number: JP-AS-006-246		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1107	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1995	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Metal	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1-1 metal sliding, 1/1 vinyl sash
24. Vernacular or property type: Minimal Traditional	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style: Minimal Traditional	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Vinyl	
27. No. of stories: 1	34. Foundation material CMU	
28. No. of bays (1st floor): 3	35. Basement type: Crawl Space	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Side-gabled	36. Front porch type/placement: Stoop	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

This resource was constructed in 1995.

This resource is less than fifty years of age and it does not exhibit exception significance necessary to merit individual listing the National Register. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling faces south and is in the north portion of the Survey Area. A concrete sidewalk abuts the south edge of the property. The lot features a large ornamental lawn. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Minimal Traditional dwelling faces south and has a rectangular footprint. It has a concrete masonry unit foundation, vinyl cladding, and corrugated metal side-gable roof. It is three bays wide and two bays deep. A one-by-one metal window occupies the first bay while a pair of one-over-one vinyl windows occupies the east bay. A wood door occupies the center bay.



1107

1107



1107



1. Survey number: JP-AS-006-247		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1108	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1996	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 4/4 vinyl sash
24. Vernacular or property type: Ranch	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material CMU	
28. No. of bays (1st floor): 4	35. Basement type: None	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Side-gabled	36. Front porch type/placement: Stoop	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

This resource was constructed in 1996.

This resource is less than fifty years of age and it does not exhibit exception significance necessary to merit individual listing the National Register. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling faces north and is in the north portion of the Survey Area. A concrete sidewalk abuts the north edge of the property and a low limestone retaining wall abuts the sidewalk. The lot features a large ornamental lawn. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Ranch dwelling faces north and has a rectangular footprint. It has a concrete masonry unit foundation, vinyl cladding, and side-gable roof with asphalt shingles. The dwelling is four bays wide. A two-car garage with an overhead door defines the east bay. Paired six-over-six vinyl windows occupy the two west bays while a wood door fills the remaining bay.





28400S HANS AVE



28400





1. Survey number: JP-AS-006-248		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1116	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1975	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance:	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 metal sash
24. Vernacular or property type: Ranch	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Brick, vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 5	35. Basement type: None	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Side-gabled	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

This resource was constructed in 1975.

This resource is less than fifty years of age and it does not exhibit exception significance necessary to merit individual listing the National Register. It is not eligible.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling faces north and is in the north portion of the Survey Area. A concrete sidewalk abuts the north edge of the property. A concrete driveway leads to the carport. The lot features a large ornamental lawn. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Ranch dwelling faces north and has a rectangular footprint. It has a concrete foundation and side-gable roof with asphalt shingles. Brick veneer clads the lower third of the dwelling while the remainder is vinyl clad. The dwelling is five bays wide and three bays deep. A front-gable porch shelters the two west bays of the primary elevation. A wood door with metal storm door fills the second-from-west bay. One-over-one metal windows with false shutters define the remaining bays. A side-gable carport projects from the west elevation and shelters a secondary entrance. An enclosed storage area with gable roof is located at the west end of the carport.







1. Survey number: JP-AS-006-249		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1212	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1910	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 wood sash
24. Vernacular or property type: Pyramid Square	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): Unknown <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Parged	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Hipped with lower cross-gable	36. Front porch type/placement: Portico	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: George W. Herron (May, sons Harry and Clifford), white, laborer car shops, rents home; 1920 city directory: Arthur Parker (Enid) - miner; 1940 Census: Harrison Harbin (Lilly, son Albert - sells papers), African American, World War Veteran, rents home, Joplin 1935; 1950 Sanborn: 1-story dwelling; 1960 city directory: John W. Brown (Neoma) - custodian First National Bank.

This resource has poor integrity. Non-historic alterations, including siding, windows, and infill of the porch, compromise the ability of this resource to convey its historic function and date of construction. It is not eligible or would not contribute to a potential historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling faces north and is in the north portion of the Survey Area. A concrete sidewalk abuts the north edge of the property and a low concrete block retaining wall abuts the sidewalk. An ornamental lawn with mature trees characterizes the landscaping. A shed outbuilding is located in the southeast corner of the lot. It has wood cladding and a shed roof. The foundation is not visible. Only the east end of the shed is visible. It retains good integrity and would be contributing to a potential historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Pyramid Square Folk House dwelling faces north and has a rectangular footprint. A shed-roof enclosed porch projects from the southwest corner and an enclosed porch forms the west half of the primary elevation. The porch enclosure is an alteration. The dwelling has a parged foundation and vinyl cladding. The pyramidal hipped roof features cross-gables and asphalt shingles. The dwelling is three bays wide and three bays deep. A one-over-one wood window occupies the east bay while a wood tripartite picture window occupies the west bay. A non-historic wood door fills the center bay and is sheltered by a non-historic gabled porch with a concrete foundation.



1212



1212





1. Survey number: JP-AS-006-250		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1218	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1910	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input type="checkbox"/> district potential <input type="checkbox"/> C <input type="checkbox"/> NC <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 6/6 vinyl sash
24. Vernacular or property type: Pyramid Square	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): c.2000 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Parged	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Hipped with lower cross-gable	36. Front porch type/placement: Stoop	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: Stewart N. Mercer (Mina, son Monty, daughters Maria, Lanora, Catherine), white; father is tailor, son is helper at dye shop, rents home; 1920 city directory: Riley Blankenship (Laura) - conductor; 1935 city directory: Same as 1940 Census; 1940 Census: George M. Allen (Flossie - maid; daughters ClaraBell, Louise; sons Barnett, Leon - chauffeur), African American, car washer, rents home, same 1935; 1950 Sanborn: 1-story dwelling; 1960 city directory: William E. Bradford (Mary) - porter First National Bank.

This resource has poor integrity. Non-historic alterations, including siding, windows and alterations to window openings, and enclosure of the porch compromise the ability of this resource to convey its historic function and date of construction. It is not eligible or would not contribute to a potential historic district.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling faces north and is in the north portion of the Survey Area. A concrete sidewalk abuts the north edge of the property. An ornamental lawn with mature trees characterizes the landscaping. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Pyramid Square Folk House dwelling faces north and has a rectangular footprint. A shed-roof enclosed porch projects from the south elevation and an enclosed porch forms the east half of the primary elevation. The porch enclosure is an alteration. The dwelling has a parged foundation and vinyl cladding. The hipped roof features cross-gables and asphalt shingles. The dwelling is three bays wide and three bays deep. Six-over-six vinyl windows occupy the east and west bays. A non-historic wood door with a metal grille fills the center bay.





1218

1218

1218



1. Survey number: JP-AS-006-251		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1302	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1910	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input checked="" type="checkbox"/> C <input type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Bungalow/Bungalowoid	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): c.1945 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Asbestos	Endangered by:
27. No. of stories: 1	34. Foundation material Not Visible	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Hipped	36. Front porch type/placement: Open, full-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district	Other:	
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: Roll C. Stewart (Florence, daughter Gladys, and son Clifford), white, miner at lead and zinc mine, rents home; 1920 city directory: vacant; 1950 Sanborn: 1-story dwelling; 1960 city directory: Mrs. Rose L. Schiltz - cleaner Joplin Rug.

This resource has good integrity. This resource would be contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling faces north and is in the north portion of the Survey Area. An east-west gravel alley abuts the south edge of the property. A concrete walkway and stairs leads to the front porch. An ornamental lawn with mature trees characterizes the landscaping. A historic garage outbuilding is located in the southeast corner of the lot. The front-gable garage has wood cladding and exposed rafter tails. A pair of historic, hinged wood doors occupies the primary elevation bay. The garage retains good integrity and would be contributing to a potential historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This bungalow dwelling faces north and has a rectangular footprint. It has asbestos shingle cladding and a hipped asphalt roof. The dwelling is three bays wide and three bays deep. An open porch with parged masonry walls, piers, and columns spans the primary elevation. One-over-one vinyl windows occupy the east and west bays while the primary entrance defines the center bay. The door is not visible.



1302







1. Survey number: JP-AS-006-252		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1316	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1915	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input checked="" type="checkbox"/> C <input type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 wood sash
24. Vernacular or property type: Bungalow/Bungalowoid	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): c.2000 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Parged	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Gable-on-hip	36. Front porch type/placement: Recessed, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1920 city directory: Norman Key (Maude) - driver Newman's; 1950 Sanborn: 1-story dwelling; 1960 city directory: James N. Varner (Della).

This resource has fair integrity. Some non-historic alterations, including the application of non-historic siding, compromises its integrity slightly. However, this resource retains integrity through its form and windows, which is sufficient to convey its historic associations and date of construction.. This resource would be contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling faces north and is in the north portion of the Survey Area. An east-west gravel alley abuts the south edge of the property. A concrete walkway and stairs leads to the front porch. An ornamental lawn with mature trees characterizes the landscaping and a chain-link fence encircles the lot. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This bungalow dwelling faces north and has a rectangular footprint. It has a parged foundation and vinyl cladding. The front-gable roof is asphalt. The dwelling is three bays wide and three bays deep. A hipped-roof porch spans the primary elevation. The west half is enclosed while the open east half has decorative metal support posts. A pair of one-over-one metal windows occupies the east bay while a single one-over-one metal window occupies the west bay. The center bay contains a non-historic wood door.







1. Survey number: JP-AS-006-253		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1318	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1915	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input checked="" type="checkbox"/> C <input type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Bungalow/Bungalowoid	31. Chimney placement: Center, straddle ridge	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): c.2000 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Parged	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Gable-on-hip	36. Front porch type/placement: Recessed, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1950 Sanborn: 1-story dwelling; 1960 city directory: Mrs. Inez B. English - widow Carl.

This resource has fair integrity. Some non-historic alterations, including the application of non-historic siding, compromises its integrity slightly. However, it retains its historic form and porch elements, sufficient to convey its historic associations and date of construction. This resource would be contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling faces north and is in the north portion of the Survey Area. An east-west gravel alley abuts the south edge of the property. A concrete walkway and stairs leads to the front porch. An ornamental lawn with mature trees and shrubs characterizes the landscaping. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This bungalow dwelling faces north and has a rectangular footprint. It has a parged foundation and vinyl cladding. The front-gable roof is asphalt. The dwelling is three bays wide and three bays deep. A hipped-roof porch spans the primary elevation. Squared wood posts on concrete block piers support the porch roof. One-over-one vinyl windows occupies the east and west bays while a non-historic fiberglass door occupies the center bay. A short brick chimney pierces the roof ridge.



1318



1318



1. Survey number: JP-AS-006-254		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1326	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1955	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input checked="" type="checkbox"/> C <input type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 wood sash
24. Vernacular or property type: Ranch	31. Chimney placement: Offset right, front slope, exterior	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Brick	Endangered by:
27. No. of stories: 1	34. Foundation material Not Visible	
28. No. of bays (1st floor): 5	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 2
29. Roof type: Hipped with lower cross-gable	36. Front porch type/placement: Recessed, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1960 city directory: Charles Q. Clay (Paralee) - clerk Post Office; Charles Clay, Jr. - US Navy.

This resource has good integrity. This resource would be contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling faces north and is in the north portion of the Survey Area. An east-west gravel alley abuts the south edge of the property. An ornamental lawn lined with mature trees and hedges characterizes the landscaping. Dense vegetation eliminates visibility of outbuildings from the public right-of-way. Constructed c. 1980, They are both less than fifty years of age would be non-contributing to the potential historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Ranch dwelling faces north and has a rectangular footprint. It has brick cladding and an asphalt roof. The foundation is not visible. The dwelling is five bays wide. The center three bays recede, creating an open porch. The porch has a metal awning, concrete masonry unit foundation, and decorative metal support posts. A single-car overhead garage door occupies the first bay and a non-historic wood pedestrian door occupies the second bay. A wood tripartite picture window occupies the third bay while a one-over-one window with a metal awning occupies the last bay. A distinctive broad brick chimney defines the fourth bay and pierces the roofline.









1. Survey number: JP-AS-006-255		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1402	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1920	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input checked="" type="checkbox"/> C <input type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Open Gable/Gambrel Front	31. Chimney placement: Center, straddle ridge	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): c.1990 <input checked="" type="checkbox"/> Altered Date(s): c.1950, c.1990 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Asbestos	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 2	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Front-gabled	36. Front porch type/placement: Portico	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1920 city directory: William L. Rogers (Mary) - meat cutter; 1935 city directory: Same as 1940 Census; 1940 Census: Allen Epperson (Wanda, daughter Patricia Ann), white, insulation department at Eagle Picher, owns home, same 1935; 1950 Sanborn: 1-story dwelling; 1960 city directory: Lonnie D. Hackney (Minnie) - janitor Gas Service.

This resource has good integrity. The asbestos siding is not original, but it is likely a historic alteration, as is the enclosure of the front porch. The replacement windows are a non-historic alteration. This resource would be contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling faces north and is in the north portion of the Survey Area. An east-west gravel alley abuts the south edge of the property. An ornamental lawn with mature trees and shrubs characterizes the landscaping. A gravel driveway to the west of the dwelling leads to a detached garage. A historic gabled garage fronts the gravel drive. It has an asphalt roof with exposed rafter tails and asbestos shingle cladding. The vehicular bay lacks a door. This garage has good integrity and would be contributing to a potential historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This one-story dwelling faces south and has a rectangular footprint. It has a concrete foundation asbestos shingle cladding, and an asphalt front-gable roof. The roof features a centered, parged straddle-ridge chimney. The dwelling is two bays wide and three bays deep. A shed-roof enclosed porch forms the primary elevation and a shed-roof addition spans the north portion of the west elevation. A pair of one-over-one vinyl windows occupies the east bay of the primary elevation while a non-historic wood door with glazing occupies the west bay. A metal awning with decorative metal support posts shelters the entrance.









1. Survey number: JP-AS-006-256		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1408	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1910	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input checked="" type="checkbox"/> C <input type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 6/6 vinyl sash
24. Vernacular or property type: Pyramid Square	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): c.2010 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1	34. Foundation material Stone	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 1
29. Roof type: Hipped with lower cross-gable	36. Front porch type/placement: Open, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		
Date(s):		



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: Dennis Ryan (Fayette), white, policeman, rents; 1920 city directory: Bert W. McCubbin (Maggie) - contractor; 1935 city directory: Same as 1940 Census; 1940 Census: Bert W. McCubbins (Maggie), white, building contractor, owns home, same 1935; 1950 Sanborn: 1-story dwelling; 1960 city directory: Mrs. Allie S. Reaves - widow Andy.

This resource has fair integrity. It retains its historic form and porch elements, sufficient to convey its historic associations and date of construction. This resource would be contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling faces north and is in the north portion of the Survey Area. An east-west gravel alley abuts the south edge of the property. An ornamental lawn with mature trees characterizes the landscaping. A one-and-a-half story gambrel-roof outbuilding is located in the southeast quarter of the lot. It has an asphalt roof and vinyl cladding. A non-historic one-by-one metal window occupies the first story bay while a non-historic casement window occupies the upper half story bay. A pedestrian entrance is located on the secondary elevation. This outbuilding has poor integrity and would be non-contributing to a potential historic district.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Pyramid Square Folk House dwelling faces north and has a rectangular footprint. It has a stone foundation and vinyl cladding. The pyramidal hipped roof features a cross-gable at the primary elevation. The dwelling is three bays wide and five asymmetrical bays deep. Six-over-six vinyl windows occupy the east and west bays while a non-historic fiberglass door occupies the center bay. A partial-width open porch shelters the west two bays. It has a shed roof, concrete foundation, and brick walls. Wood columns support the roof.



1408



1406





1. Survey number: JP-AS-006-257		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1412	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1905	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input checked="" type="checkbox"/> C <input type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input checked="" type="checkbox"/> historic <input type="checkbox"/> replacement Pane arrangement 1/1 wood sash
24. Vernacular or property type: Other Vernacular	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): Unknown <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Vinyl	Endangered by:
27. No. of stories: 1.5	34. Foundation material Not Visible	40. No. of outbuildings (describe in box 40 cont.): 0
28. No. of bays (1st floor): 3	35. Basement type: Unknown	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>
29. Roof type: Hipped	36. Front porch type/placement: Open, full-width	

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district	Other:	
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1910 Census: Seymour Wells (Jeanette, son Claude, daughter Gertrude), white, miner lead and zinc mines, rents; 1920 city directory: Seymour Wells (Jeanette); 1940 Census: Homer Tedder (Pauline - gold stamping at Meekers; daughters Joan and Barbara), white, furniture store, rents home, Joplin MO 1935; 1950 Sanborn: 2-story dwelling; 1960 city directory: Rev. William M. Kelley (Minnie).

This resource has poor integrity. The upper story alteration compromises the integrity of the dwelling. This resource would be non-contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling faces north and is in the north portion of the Survey Area. An east-west gravel alley abuts the south edge of the property. A concrete walkway leads to the front porch and an ornamental lawn with mature trees characterizes the landscaping. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This dwelling faces north and has a rectangular footprint. It has a masonry foundation and vinyl cladding. The complex roof has asphalt shingles and wood fascia boards. Hipped dormers are located on the east and west roof slopes while a gablet is present on the primary slope. The dwelling is three bays wide and three bays deep. A non-historic open, full-width porch shelters the primary elevation bays. It has a hipped roof, wood support posts, and a matchstick balustrade. A non-historic wood door occupies the center bay while one-over-one wood windows occupy the remaining bays. A bay window projects from the east elevation and has a gabled roof.







1. Survey number: JP-AS-006-258		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1422	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1920	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input checked="" type="checkbox"/> C <input type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input checked="" type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Asphalt	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Bungalow/Bungaloid	31. Chimney placement: Center, straddle ridge	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input type="checkbox"/> Altered Date(s): Unknown <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape L-shaped	33. Exterior wall cladding: Hardboard	Endangered by:
27. No. of stories: 1	34. Foundation material Concrete	
28. No. of bays (1st floor): 3	35. Basement type: None	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Front-gabled	36. Front porch type/placement: Recessed, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1920 city directory: Fred Haase (Emma) - core maker United Iron Works Inc.; 1940 Census: Vivion Berry (Gladys), white, carpenter, rents home, Joplin MO 1935; 1950 Sanborn: 1-story dwelling; 1960 city directory: Edward A. Berry (Opal).

This resource has fair integrity. It retains its historic form and porch, sufficient to convey its historic associations and date of construction. This resource would be contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling faces north and is in the north portion of the Survey Area. An east-west gravel alley abuts the south edge of the property. A concrete walkway leads to the front porch and an ornamental lawn with mature trees characterizes the landscaping. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This bungalow dwelling faces north and has an L-shaped footprint. It has a concrete foundation and pressboard siding. The front-gable roof features asphalt and wood brackets. A short brick chimney pierces the ridge. The dwelling is three bays wide and three bays deep. The east two bays of the primary elevation slightly recede, creating a partial-width open porch. The porch has a concrete foundation and squared wood columns support the front-gable roof. One-over-one vinyl windows with flat board trim and false shutters occupy the east and west bays while a non-historic wood door occupies the center bay. A modern carport projects from the west elevation while a wood privacy fence obscures the east elevation.



1422



1422



1. Survey number: JP-AS-006-259		2. Survey Name: East Town (Original Joplin) Historic Survey Phase 1	
3. County: JASPER		4. Address 1424	Street (name): E. North Street
5. City: Joplin	Vicinity <input type="checkbox"/>	7. Township/Range/Section: T: R: S:	
8. Historic name (if known):		9. Present/other name (if known):	
10. Ownership: <input checked="" type="checkbox"/> Private <input type="checkbox"/> Public		11a. Historic use (if known): Domestic/Single Dwelling	11b. Current use: Domestic/Single Dwelling

HISTORICAL INFORMATION

12. Construction date: 1920	15. Architect:	18. Previously surveyed? <input type="checkbox"/> Cite survey name in box 22 cont. (page 3)
13. Significant date/period 1880 - 1970	16. Builder/contractor:	19. On National Register? <input type="checkbox"/> individual <input type="checkbox"/> district Cite nomination name in box 22 cont. (page 3)
14. Area(s) of significance: Community Planning & Development, and Ethnic History/Black.	17. Original or significant owner:	20. National Register eligible? <input type="checkbox"/> individually eligible <input checked="" type="checkbox"/> district potential <input checked="" type="checkbox"/> C <input type="checkbox"/> NC <input type="checkbox"/> not eligible <input type="checkbox"/> not determined
21. History and significance on continuation page. <input type="checkbox"/>		22. Sources of information on continuation page. <input checked="" type="checkbox"/>

ARCHITECTURAL INFORMATION

23. Category of property: <input checked="" type="checkbox"/> building <input type="checkbox"/> site <input type="checkbox"/> structure <input type="checkbox"/> object	30. Roof material: Metal	37. Windows: <input type="checkbox"/> historic <input checked="" type="checkbox"/> replacement Pane arrangement 1/1 vinyl sash
24. Vernacular or property type: Pyramid Square	31. Chimney placement: N/A	38 Acreage (rural) Visible from public road? <input checked="" type="checkbox"/>
25. Style:	32. Structural system: Frame	39. Changes (describe in box 41 cont.): <input checked="" type="checkbox"/> Addition(s) Date(s): <input checked="" type="checkbox"/> Altered Date(s): 2017 <input type="checkbox"/> Moved Date(s): <input type="checkbox"/> Other Date(s):
26. Plan shape Rectangular	33. Exterior wall cladding: Hardboard	Endangered by:
27. No. of stories: 1	34. Foundation material Parged	
28. No. of bays (1st floor): 3	35. Basement type: Unknown	40. No. of outbuildings (describe in box 40 cont.): 0
29. Roof type: Hipped	36. Front porch type/placement: Veranda, partial-width	41. Further description of building features and associated resources on continuation page. <input checked="" type="checkbox"/>

OTHER

42. Current owner/address:	43. Form prepared by (name and org.): Rosin Preservation, LLC Rachel Barnhart 1712 Holmes Kansas City, MO 64108 816-472-4950 rachelb@rosinpreservation.com	44. Survey date: 5/1/2018
		45. Photographer: Brad Finch, f-stop Photography

FOR SHPO USE

Date entered in inventory:	Level of survey <input type="checkbox"/> reconnaissance <input type="checkbox"/> intensive	Additional research needed? <input type="checkbox"/> yes <input type="checkbox"/> no
National Register Status: <input type="checkbox"/> listed <input type="checkbox"/> in listed district		Other:
Name: <input type="checkbox"/> pending listing <input type="checkbox"/> eligible (individually) <input type="checkbox"/> eligible (district) <input type="checkbox"/> not eligible <input type="checkbox"/> not determined		

Date(s):



ADDITIONAL INFORMATION

21. (cont.) History and significance. Expand box as necessary, or add continuation pages.

A chronological list of occupants includes: 1920 city directory: Ora Doyle (Mollie) - laborer; Walton Doyle - laborer; 1940 Census: Ralph Dodson (Evelyn, son Ralph) white, truck driver M & O Service, rents home, Muskogee OK, 1935; 1950 Sanborn: 1-story dwelling; 1960 city directory: Bob J. Peppers (Audrey) - machinist Mid-Western Machinery.

This resource has fair integrity due to the alterations to the window openings. It retains its historic form and porch, sufficient to convey its historic associations and date of construction. This resource would be contributing to the East Joplin Residential Historic District, significant for its associations with the early residential development of Joplin, specifically the African American community. Areas of significance are Community Planning & Development, and Ethnic History/Black.

22. (cont.) Sources of information. Expand box as necessary, or add continuation pages.

Google Earth, 2018; Joplin City Directory, 1920-1968; United States Census, 1910-1940; Sanborn Map Company. Joplin, Jasper County, Missouri, 1884-1950.

40. (cont.) Description of environment and outbuildings. Expand box as necessary, or add continuation pages.

The dwelling faces north and is in the north portion of the Survey Area. An east-west gravel alley abuts the south edge of the property while a concrete sidewalk abuts the north edge. A low, stone retaining wall abuts the sidewalk. A concrete walkway leads to the front porch and an ornamental lawn with mature trees characterizes the landscaping. No outbuildings were observed.

41. (cont.) Description of primary resource. Expand box as necessary, or add continuation pages.

This Pyramid Square Folk House dwelling faces north and has a rectangular footprint. The dwelling is three bays wide and four asymmetrical bays deep. It has a parged foundation, standing seam metal roof, and pressboard siding. A hipped-roof porch projects from the front slope of the dwelling's hipped roof and shelters the entrance. The porch has a concrete foundation and wood columns on concrete block piers support the roof. One-over-one vinyl windows occupy the east and west bays while a non-historic fiberglass door occupies the center bay. The windows are smaller than the historic openings, requiring infill around them. A modern carport projects from the west elevation while a wood privacy fence obscures the east elevation.



1424

LOWE'S

LO



1424

Lo

LOWE'S

S

LOWE'S

LOWE'S

LOWE'S